



Funkregulatorische Hinweise / Radio regulatory information / Información reglamentaria de radiocomunicaciones / Information radoréglementaire / Informação sobre regulamentação radioelétrica / Радио регуляторне информације / Нормативна інформація про радіо / 無線規制情報 / 무선 규제 정보 / 無線電監管資訊
Alle VW PKW Modelle / All VW Car Models / Todos los modelos de coches VW / Tous les modèles de voitures VW / Todos os modelos de carros VW / Сви ВВ модели аутомобила / Всі моделі автомобілів VW / すべての VW 車種 / 모든 폭스바겐 자동차 모델 / 所有大眾汽車 車型

Funkregulatorische Hinweise / Radio regulatory information / Información reglamentaria de radiocomunicaciones / Information radoréglementaire / Informação sobre regulamentação radioelétrica / Радио регуляторне информације / Нормативна інформація про радіо / 無線規制情報 / 무선 규제 정보 / 無線電監管資訊

Alle VW PKW Modelle / All VW Car Models / Todos los modelos de coches VW / Tous les modèles de voitures VW / Todos os modelos de carros VW / Сви ВВ модели аутомобила / Всі моделі автомобілів VW / すべての VW 車種 / 모든 폭스바겐 자동차 모델 / 所有大眾汽車 車型

Genehmigungsnummern

Certificates / Certificados / Certificates / Сертификаты / Цертификате / 証明書 / 證書 / 인증서

Weitere Einträge unter / More entries at / Más entradas en / Mais entradas em / Plus d'entrées sur / Більше записів на / Више уноса на / その他のエントリ / 更多條目位於 / 더 많은 항목 :

www.volkswagen.com/generalinfo

República Argentina



C-17908: ARS4-B, H-21902: 17101002, C-22292: ARS5-B, H-26251: BR21, H-27278: F5CP42, C-26978: MIB3 OI VR-E, C-22036: MIB3 OI, H-27598: MRR1Plus, H-27726: FR5CUEC, H-22390: FS14T, H-22391: FS14TK, H-22794: 1710132_MQB_AB_Medium, H-22793: 17101054 Roadmap, C-15806: MIB2 Entry L69SE2, C-15807: MIB2 Entry L69VW2, H-22757: 0869_129 Koppelantenne Gen 3, H-27976: RS5.3, C-23301: MIB3 OI, C-23466: ConBox High Offline, H-23129: FS125C, H-27923: FS19, H-15700: FS94, H-22961: FS19, C-23301: MIB3 OI, C-23466: Conbox High Offline, H-24102: TSSRE4Uf, H-16681: FS1744, H-24262: WCH-183, H-24260: WCH-186, H-20816: BCM37WBL, H-24258: WCH-186, H-24470: WCH-186, H-24469: WCH-186, H-24442: 18100931_MQB_MY18-19+20, H-28829: Colour 5C, H-28830: Medium 5C, H-24261: WCH-185, H-25893: WPC-003-1, H-27977: RS5.5, H-29401: TSSRE4Td, H-17568: MQB-B B Kessy, H-24892: Compensor LTE, H-17563: 5ZA010176, H-17567: MQB-A Kessy, H-17562: MQB-B H-A Kessy, C-25101: BSD 3.0, C-25102: RS4, H-12804: FS09, H-21050: FS1744M, H-24931: FPK8 IM-MOSD, H-20030: MRR1e4FCR, H-28774: FS1915, H-28773: FS195, H-21050: FS1744M, C-21673: TSSRE4A, C-21672: LRR4, H-28773: LRR4R, C-25803: Tranceptor BY-OC RSE, H-25531: NSS, C-17604: FK42 MIB STD2 PQ, C-30067: FK42 MIB3 OI nf, H-30374: TLVUM3IU-W-, H-28912: BR22, H-27594: UWBTRX22, H-29168: MIB3GP, H-29314: MIB3 OI VR-E, H-29107: MIB3 OI, H-26251: BR21, H-21901: 17101001, H-30781: TKCMOD, H-21902: 17101002, H-21797: MRR EVO14F, H-21798: MRR1REAR, H-25533: OCU TLV, H-25097: OCU TLV, C-17908: ARS4-B, C-27899: PC003-5, H-21796: VK2, H-21624: FS14P70M, C-26724: MIB2 Main Unit, C-22292: ARS5-B, H-22192: 17101043, H-22363: 17101056, H-22364: 17101057, H-22191: 18020531, H-22362: 18020532, C-22394: FR5CPEC, H-27278: F5CP42, C-22181: MIB STD2 ZR, H-27976: RS5.3, H-27977: RS5.5, H-22302: BCMevo2, H-22962: FS197, H-22856: 013854, H-22036: MIB3 OI, H-27899: WPC003-5, H-32069: HFA31, H-23129: FS125C,

H-22391: FS14TK, H-15700: FS94, H-22390: FS14T, H-22961: RS819, C-23466: CONBOX_HIGH, H-32212: I25U, H-32213: I25B, H-28365: E3HCP422, H-28016: BCM37WBL, H-23423: BCMevoC, H-24012: TSSRE4Uf, H-33176: TMSS5H4, H-28774: FS1915, H-28773: FS195, H-16681: FS1744, H-24262: WCH-183, H-24258: WCH-186b, H-24260: WCH-186a, H-33270: MIB3 TOP, H-28912: BR22, H-29120: WCH-304

République du Bénin

AGREE PAR L'ARCEP BENIN

Numéro d'agrément_Date d'agrément:

016/ARCEP/SE/DJPC/DR/GU/2021, 018/ARCEP/SE/DR/DAJRC/GU/2019, 069/ARCEP/SE/DR/DAJRC/GU/2019, 073/ARCEP/SE/DR/DAJRC/GU/2019, 074/ARCEP/SE/DR/DAJRC/GU/2019, 075/ARCEP/SE/DAR/DJPC/GU/2020, 114/ARCEP/SE/DR/DAJRC/GU/2017, 115/ARCEP/SE/DR/DAJRC/GU/2017, 115/ARCEP/SE/DR/DAJRC/GU/2019, 121/ARCEP/SE/DR/DAJRC/GU/2019, 123/ARCEP/SE/DR/DAJRC/GU/2018, 124/ARCEP/SE/DR/DAJRC/GU/2018, 124/ARCEP/SE/DR/DAJRC/GU/2019, 133/ARCEP/SE/DR/DAJRC/GU/2018, 137/ARCEP/SE/DR/DAJRC/GU/2019, 138/ARCEP/SE/DR/DAJRC/GU/2019, 143/ARCEP/SE/DR/DAJRC/GU/2018, 165/ARCEP/SE/DR/DAJRC/GU/2018, 166/ARCEP/SE/DR/DAJRC/GU/2018, 167/ARCEP/SE/DR/DAJRC/GU/2018, 171/ARCEP/SE/DJPC/DAR/GU/2020, 173/ARCEP/SE/DR/DAJRC/GU/2018, 175/ARCEP/SE/DR/DAJRC/GU/2018, 176/ARCEP/SE/DR/DAJRC/GU/2018, 177/ARCEP/SE/DR/DAJRC/GU/2018, 179/ARCEP/SE/DR/DAJRC/GU/2018, 209/ARCEP/SE/DR/DAJRC/GU/2019, 211/ARCEP/SE/DR/DAJRC/GU/2019, 213/ARCEP/SE/DR/DAJRC/GU/2018, 216/ARCEP/SE/DR/DAJRC/GU/2018, 316/ARCEP/SE/DJPC/DAR/GU/2020, 065/ARCEP/SE/DJPC/DAR/GU/2021, 016/ARCEP/SE/DJPC/DAR/GU/2021

2018-149/ARCEP/PT/DAJRC/GU, 2018-150/ARCEP/PT/DAJRC/GU, 2020-274/ARCEP/PT/SE/DAF/DJPC/DAR/GU, 2021-069/ARCEP/PT/SE/DAF/DJPC/DAR/GU, 2021-097/ARCEP/PT/SE/DJPC/DAR/GU, 2022-019/ARCEP/PT/DAJRC/GU, 2022-286/ARCEP/PT/DAJRC/GU, 2022-287/ARCEP/PT/DAJRC/GU, 2023-034/ARCEP/PT/DJPC/DAR/DCT/GU, 2023-075/ARCEP/SE/DJPC/DAR/DCT/GU, 2023-072/ARCEP/SE/DJPC/DAR/DCT/GU, 2023-088/ARCEP/SE/DJPC/DAR/DCT/GU, 2023-118/ARCEP/SE/DJPC/DAR/DCT/GU, 2023-137/ARCEP/SE/DAR/DCT/GU, 2023-176/ARCEP/SE/DAR/DCT/GU, 2023-180/ARCEP/SE/DAR/DCT/GU, 2023-183/ARCEP/SE/DAR/DCT/GU, 2023-181/ARCEP/SE/DAR/DCT/GU, 2023-182/ARCEP/SE/DAR/DCT/GU, 2023-184/ARCEP/SE/DAR/DCT/GU, 2023-345/ARCEP/SE/DAR/DCT/GU, 2023-250/ARCEP/SE/DAR/DAR/GU, 2023-072/ARCEP/SE/DJPC/DAR/GU, 2023-283/ARCEP/SE/DAR/GU, 2023-281/ARCEP/SE/DAR/GU, 2023-284/ARCEP/SE/DAR/GU, 2023-271/ARCEP/SE/DAR/GU, 2024-231, 2024-40, 2024-52, 2023-317, 2024-282, 2024-118, 2024-117, 2025-89

República Federativa do Brasil

Para maiores informações, consulte o site da ANATEL - www.anatel.gov.br.



ANATEL 00716-15-03745, ANATEL 00850-13-03745, ANATEL 0939-14-2856,
 ANATEL 0940-14-2856, ANATEL 00231-20-09215, ANATEL 00716-15-03745,
 ANATEL 00720-19-05364, ANATEL 00939-19-06673, ANATEL 01094-17-03226,
 ANATEL 01095-17-03226, ANATEL 01138-12-02856, ANATEL 01140-12-02856,
 ANATEL 01202-15-06815, ANATEL 01618-20-02149, ANATEL 01760-20-02149,
 ANATEL 01812-19-05364, ANATEL 01813-19-05364, ANATEL 01814-19-05364,
 ANATEL 01834-18-02856, ANATEL 02018-18-04557, ANATEL 02144-17-03430,
 ANATEL 02294-15-03616, ANATEL 02318-12-02856, ANATEL 02393-19-05364,
 ANATEL 02450-17-02010, ANATEL 02452-17-02010, ANATEL 02992-14-06673,
 ANATEL 03764-17-05386, ANATEL 03833-18-06353, ANATEL 03834-18-06353,
 ANATEL 03993-19-10188, ANATEL 04057-14-06068, ANATEL 04282-19-01925,
 ANATEL 04383-18-06673, ANATEL 04708-15-05364, ANATEL 04998-19-02405,
 ANATEL 04999-19-02405, ANATEL 05273-18-02496, ANATEL 05292-18-06353,
 ANATEL 05293-18-06353, ANATEL 05296-18-06353, ANATEL 05297-18-06353,
 ANATEL 05310-19-10188, ANATEL 05505-18-06353, ANATEL 05506-18-06353,
 ANATEL 05507-18-06353, ANATEL 05508-18-06353, ANATEL 05509-18-06353,
 ANATEL 05511-18-06353, ANATEL 05512-18-06353, ANATEL 05531-16-02149,
 ANATEL 05674-16-06830, ANATEL 05676-19-01925, ANATEL 05803-21-03745,
 ANATEL 06029-18-05364, ANATEL 06215-16-03430, ANATEL 06763-18-06353,
 ANATEL 06950-18-10457, ANATEL 06962-18-06353, ANATEL 07084-18-03745,
 ANATEL 07137-19-08137, ANATEL 07183-18-06353, ANATEL 07184-18-06353,
 ANATEL 07185-18-06353, ANATEL 07186-18-06353, ANATEL 07188-18-06353,
 ANATEL 07189-18-06353, ANATEL 07191-18-06353, ANATEL 07830-17-08001,
 ANATEL 08057-19-05179, ANATEL 09036-19-01925, ANATEL 09087-19-07978,
 ANATEL 09275-18-06353, ANATEL 10313-20-06353, ANATEL 12001-20-10944,
 ANATEL 13806-20-09215, ANATEL 00533-22-03745, ANATEL 05310-19-10188,
 ANATEL 11718-22-05364, ANATEL 11502-22-05364, ANATEL 05507-18-06353,
 ANATEL 11718-22-05364, ANATEL 11502-22-05364, ANATEL 01812-19-05364, Ver-
 sys2293_17/07/2025, ANATEL ANATEL Versys2259_21/03/2025, ANATEL Ver-
 sys2442_22/02/2025, ANATEL Versys2890_15/12/2024, ANATEL Ver-
 sys2989_01/08/2025, ANATEL Versys4241_27/12/2024, ANATEL Ver-
 sys3022_14/10/2025, ANATEL Versys3889_13/08/2026, ANATEL Ver-
 sys4627_17/06/2026, ANATEL Versys2181_05/10/2026, ANATEL Ver-
 sys4570_01/07/2026, ANATEL Versys4016_11/05/2025, ANATEL Versys
 2442_22/02/2027

ANATEL 0148-15-7978, ANATEL 0263-16-9946, ANATEL 0278-15-7978,
 ANATEL 0456-15-9946, ANATEL 0646-13-5452, ANATEL 0716-15-3745,
 ANATEL 0850-13-3745, ANATEL 0918-14-5364, ANATEL 1140-14-2856,
 ANATEL 1202-14-6815, ANATEL 1497-14-9946, ANATEL 1498-14-9946,
 ANATEL 1546-10-2886, ANATEL 1690-15-5364, ANATEL 1711-12-5364,
 ANATEL 2115-15-6815, ANATEL 2220-14-3745, ANATEL 2230-14-3745,
 ANATEL 2294-15-3616, ANATEL 2483-14-6324, ANATEL 3002-09-3745,
 ANATEL 3080-14-6828, ANATEL 3557-15-5364, ANATEL 4057-14-6068,
 ANATEL 02128-16-05364, ANATEL 02530-16-09946, ANATEL 03323-18-02930,
 ANATEL 05531-16-02149, ANATEL 05674-15-06830, ANATEL 05674-16-06830,
 ANATEL 07084-18-03745, ANATEL 00278-15-07978, ANATEL 05676-19-01925,
 ANATEL 14707-21-01925, ANATEL 08795-23-01925, ANATEL 08004-23-09215,
 ANATEL 11743-23-07978, ANATEL UL-BR 17.0958,
 ANATEL MT-6294/2022_17/01/2025, ANATEL MT-6412/2023_12/04/2025,
 ANATEL MT-6452/2023_14/06/2025, ANATEL MT-6401/2023_12/04/2025,
 ANATEL NCC10909/14, ANATEL NCC10809/14, ANATEL DEKRA-00025-22,
 ANATEL DKTEL-00198-23_05/02/2025, ANATEL UL-BR 23.0140_03/07/2025,
 ANATEL UL-BR 23.1314_08/09/2025, ANATEL UL-BR 23.1378_27/11/2025
 ANATEL UL-BR23.1707_04/12/2025, ANATEL BRC-24.2893_14/10/2026,
 ANATEL MT-3003/2014_22/08/2026, ANATEL BRC-23.1869_22/06/2025,
 ANATEL 20117-23-10187_07/02/2026, ANATEL UL-BR 24.0099_07/02/2026,
 ANATEL CPQD11808_19/04/2026, ANATEL 05213-24-03798_10/05/2026,

ANATEL MT-6842/2024_31/07/2026, ANATEL MT-6870/2024_15/07/2026,
 ANATEL 07084-18-03745_05/10/2026, ANATEL MT-6869/2024_15/07/2026,
 ANATEL 05602-24-10457_02/07/2026, ANATEL MT-6828/2024_05/06/2026,
 ANATEL 01711-12-05364_23/07/2026, ANATEL 07183-18-06353_09/10/2026,
 ANATEL MT-6077/2022_13/09/2026, ANATEL 01711-12-05364_23/07/2026,
 ANATEL NCC 26498/24_13/02/2026, ANATEL NCC 26499/24_10/02/2026,
 ANATEL Versys 2574_06/09/2026, ANATEL MT-6924/2024_25/07/2026,
 ANATEL MT-6270/2022_20/12/2026, ANATEL MT-6272/2022_20/12/2026,
 ANATEL CPQD 9730_21/12/2026, ANATEL MT-3900/2016_06/12/2026,
 ANATEL MT-6123/2022_26/10/2026, ANATEL MT-6109/2022_04/02/2027,
 ANATEL Versys 4241_28/12/2026, ANATEL MT-6294/2023_17/01/2027,
 ANATEL DEKRA-00198-23_05/02/2027, ANATEL MT-5192/2022_12/02/2027,
 ANATEL MT-6246/2022_12/04/2027, ANATEL MT-6341/2023_02/04/2027,
 ANATEL MT-6401/2023_12/04/2027, ANATEL 00278-15-07978_05/02/2027,
 ANATEL 04057-14-06068_11/02/2027, ANATEL Versys 2227_19/03/2027,
 ANATEL NCC 26993/24_09/02/2027, ANATEL 00574-25-07978_30/01/2027,
 ANATEL BRC-22.1394.01_16/02/2027, ANATEL NCC27376/25_30/03/2027,
 ANATEL Versys 4016_11/05/2027, ANATEL Versys 2293_17/07/2027,
 ANATEL Versys 2989_01/08/2027, ANATEL UL-BR 23.0649_06/06/2027,
 ANATEL 03563-17-05364_14/06/2027, ANATEL BRC-25.5539.01_16/06/2027,
 ANATEL MT-7183/2025_16/06/2027, ANATEL 02950-25-05364_02/07/2027,
 ANATEL MT-7225/2025_02/07/2027, ANATEL 03890-25-15869_09/07/2027,
 ANATEL Versys 2384_23/08/2027, ANATEL 04142-25-15869_27/07/2027,
 ANATEL MT-6594_13/10/2027, ANATEL MT-7231/2025_01/08/2027,
 ANATEL Versys 3022_14/10/2027, ANATEL MT-6718/2023_21/12/2027,
 ANATEL 14707-21-01925_24/08/2027, ANATEL MT-6653/2023_24/10/2027,
 ANATEL Versys 4984_09/2027, ANATEL MT-6722/2023_20/03/2028,
 ANATEL 05502-25-06643_25/09/2027, ANATEL Versys 2433_28/11/2027,
 ANATEL Versys 5047_08/10/2027, ANATEL 06554-25-07978_25/09/2027,
 ANATEL 12001-20-10944_18/09/2027, ANATEL NCC 28481/25_04/12/2027,
 ANATEL Versys 3083_19/01/2027, ANATEL Versys 3083_19/01/2027, ANATEL Ver-
 sys 3083_19/01/2027, ANATEL UL-BR 26.0209_07/02/2028

Este equipamento não tem direito à proteção contra interferência prejudicial e não pode causar interferência em sistemas devidamente autorizados. Para maiores informações, consulte o site da ANATEL- www.anatel.gov.br

Este equipamento opera em caráter secundário, isto é, não tem direito à proteção contra interferência prejudicial, mesmo de estações do mesmo tipo, e não pode causar interferência a sistemas operando em caráter primário. Para maiores informações, consulte o site da ANATEL- www.anatel.gov.br

ANATEL 10530-23-04457, ANATEL 10531-23-04457, ANATEL 10532-23-04457,
 ANATEL 10537-23-04457, ANATEL 10538-23-04457, ANATEL 03131-24-04457,
 ANATEL 00526-24-12217, ANATEL 01898-24-12217, ANATEL 01901-24-12217,
 ANATEL 15772-23-12217, ANATEL 15786-23-12217, ANATEL 20316-23-15296

República de Chile

Este equipo cumple con la Resolución Exenta 403, de 2008, y sus modificaciones, de la Subsecretaría de Telecomunicaciones del Ministerio de Transportes y Telecomunicaciones de Chile, relativa a radiaciones electromagnéticas.

www.volkswagen.com/generalinfo



ARCEP/2025, 730/ARCEP/2024, 949/ARCEP/2025, 1048/ARCEP/2025, 757/ARCEP/2025, 760/ARCEP/2025, 1139/ARCEP/2025, 1214/ARCEP/2025, 45/ARCEP/2026, 112/ARCEP/2026, 132/ARCEP/2026

England, Wales und Schottland



Approval marks for radio equipment in England, Wales and Scotland.

Further information on radio equipment and EU declarations of conformity can be found at www.volkswagen.com/generalinfo.

Länder die Funkanlagen nach EU-Richtlinien zulassen:

Weitere Hinweise zu Funkanlagen und EU-Konformitätserklärungen unter / Further information on radio equipment and EU declarations of conformity can be found at / Puede encontrar más información sobre los equipos radioeléctricos y las declaraciones de conformidad de la UE en / Para mais informações sobre equipamentos de rádio e declarações UE de conformidade, consultar / Vous trouverez de plus amples informations sur les équipements radio et les déclarations de conformité UE à l'adresse suivante: www.volkswagen.com/generalinfo.

Republique Gabonaise

D'HOMOLOGATION D'EQUIPEMENTS DE TELECOMMUNICATIONS

CERTIFICAT No:

033/ARCEP/2021, , 070/ARCEP/2021, , 419/ARCEP/2021, 421/ARCEP/2021, , , 1016/ARCEP/2021, , 1365/ARCEP/2021, 699/ARCEP/2021, 203/ARCEP/2022, 044/ARCEP/2022, 112/ARCEP/2022, 096/ARCEP/2022, 264/ARCEP/2022, 263/ARCEP/2022, 320/ARCEP/2022,319/ARCEP/2022,531/ARCEP/2022,542/ARCEP/2022,535/ARCEP/2023,540/ARCEP/2022, 95/ARCEP/2022, 604/ARCEP/2022, 602/ARCEP/2022, 601/ARCEP/2022, 600/ARCEP/2022, 618/ARCEP/2022, 642/ARCEP/2022, 641/ARCEP/2022, 640/ARCEP/2022, 790/ARCEP/2022, 890/ARCEP/2022, 892/ARCEP/2022, 891/ARCEP/2022, 1031/ARCEP/2022, 95/ARCEP/2023, 103/ARCEP/2023, 239/ARCEP/2023, 446/ARCEP/2023, 581/ARCEP/2023, 105/ARCEP/2023, 104/ARCEP/2023, 966/ARCEP/2023, 1005/ARCEP/2023, 1002/ARCEP/2023, 65/ARCEP/2024, 74/ARCEP/2024, 76/ARCEP/2024, 145/ARCEP/2024, 143/ARCEP/2024, 144/ARCEP/2024, 290/ARCEP/2024, 625/ARCEP/2024, 632/ARCEP/2024, 631/ARCEP/2024, 629/ARCEP/2024, 628/ARCEP/2024, 633/ARCEP/2024, 866/ARCEP/2024, 1096ARCEP/2024, 1097/ARCEP/2024, 1500/ARCEP/2024, 1286/ARCEP/2024, 1432/ARCEP/2024, 1287/ARCEP/2024, 1498/ARCEP/2024, 1510/ARCEP/2024, 1511/ARCEP/2024, 1550/ARCEP/2024, 1606/ARCEP/2024, 15/ARCEP/2025, 17/ARCEP/2025, 11/ARCEP/2025, 231/ARCEP/2025, 232/ARCEP/2025, 412/ARCEP/2025, 649/ARCEP/2025, 724/ARCEP/2025, 723/

Republic of Ghana

NCA Approved: XXX-XX-XXX-XXX



BRE-1M-GE2-15A, BR3-1M-GE2-X72, BR3-1M-GE2-X69, BR3-1M-GE2-080, BR3-1M-GE2-087, BR3-1M-GE2-088, BR3-1M-GE2-089, BR3-1M-GE2-09E, BR3-1M-GE2-OAF, BR3-1M-GE2-0BA, BR3-1M-GE2-0BB, BR3-1M-GE2-0BC, BR3-1M-GE2-0BO, BR3-1M-GE2-0B3, BR3-1M-GE2-0B4, BR3-1M-GE2-0B7, BR3-1M-GE2-0B8, BR3-1M-GE2-0D2, BR3-1M-GE2-0BA, BR3-1M-GE2-0BC, BR3-1M-GE2-0EC, BR3-1M-GE2-0ED, BR3-1M-GE2-0EE, BR3-1M-GE2-10A, BR3-1M-GE2-10B, BR3-1M-GE2-15A, BR3-1M-GE2-130, EX6-6M-GE2-17B, ORG-4H-7E3-X98, SRO-1M-7E4-2A9, SRO-1M-7EA-24B, SRO-1M-7E4-25D, SRO-1M-7E4-243, SRO-1M-7E4-244, SRO-1M-7E4-246, ZRO-M8-7E3-11B, ZRO-M8-7E3-19A, ZRO-M8-7E3-19C, ZRO-M8-7E3-X26, ZRO-M8-7E3-X43, ZRO-M8-7E3-X73, ZRO-M8-7E3-X75, ZRO-M8-7E3-X90, ZRO-M8-7E3-X92, ZRO-M8-7E3-X96, ZRO-M8-7E3-11B, ZRO-M8-7E3-20B, ZRO-M8-7E3-209, ZRO-M8-7E3-229, ZRO-M8-7E3-27B, ZRO-1H-7E3-14E, ZRO-1H-7E3-150, 1R3-1M-7E1-0B7, 1R3-1M-7E1-09B, 1R3-1M-7E1-09C, 1R3-1M-7E1-160, 2R9-1H-7E0-xAC, 2R9-1H-7E0-X71, 2R9-1H-7E0-X75, 2R9-1H-7E0-X90, 2R9-1H-7E0-0DA, 3R2-1M-7DF-287, 3R2-1M-7DF-288, 3R8-8M-7DF-2AA, 6X6-4H-7E0-0F3, 7E5-7M-X0B-RDR, 7E5-7M-X24-RDR, 7E5-7M-X43-RDR, 7E5-7M-X47-RDR, 7E5-7M-X74-RDR, 7T6-5H-7DF-17F, 7T6-5H-7DF-182,7E5-7M-101-RDR,7E5-7M-156-RDR,7E6-M1-X36-SRD,7E6-M1-XDC-SRD,7E6-M1-XOF-SRD, 7E6-M1-X92-SRD, 7E6-M1-XDC-SRD, 7E6-M1-XOF-SRD, 7E6-M1-216-SRD, 7E6-SH-215-SRD, 7E6-M1-12D-SRD, 7M-7E7-X93-DSR, 7M-7E7-X48-DSR, 7E6-M1-12E-SRD, 7E6-M1-12C-SRD, 7M-7E7-XE7-DSR, 7M-7E7-XA8-DSR, 7E5-7M-151-RDR, 7E6-M1-155-SRD, HS-7E7-X2B-DSR, 7E5-7M-101-RDR, HS-7E7-X2B-DSR, IH-7E8-X65-TIH, HS-7E7-173-DSR, 7M-7E7-XFO-DSR, 7M-7E7-109-DSR, 7M-7E7-XE3-DSR, 7M-7E7-XR1-DSR, 1R3-1M-7E1-160, SSRH-7E9-XE6-7M, NTH-7E9-199-HX.

State of Israel

MoC:

11-12320, 51-07681, 51-10011, 51-10360, 51-10361, 51-37428, 51-41889, 51-42830, 51-42841, 51-43949, 51-46980, 51-47851, 51-54730, 51-55347, 51-57375, 51-63653, 51-64296, 51-65008, 51-65009, 51-65839, 51-65880, 51-65909, 51-65953, 51-66171, 51-66172, 51-66173, 51-66259, 51-66383, 51-66390, 51-66415, 51-66601, 51-66602, 51-69416, 51-69417, 51-70460, 51-70461, 51-71498, 51-71601, 51-73078, 51-73720, 51-74243, 51-74291, 51-74339, 51-74361, 51-74441, 51-74442, 51-74443, 51-74436, 51-74537, 51-74636, 51-74989, 51-75000, 51-75054, 51-74632, 51-74633, 51-74634, 51-74635, 51-74636, 51-74896, 51-74989, 51-75000, 51-75054, 51-75515, 51-76029, 51-76422, 51-76971, 51-77001, 51-77882, 51-80024, 51-81786, 51-81807, 51-82314,

55-02626, 55-06864, 55-06893, 55-06894, 55-07102, 55-07460, 55-07477, 55-07480, 55-07680, 55-07681, 55-07789, 55-08250, 55-08456, 55-08739, 55-08803, 55-09135, 55-09396, 55-09600, 55-09601, 55-09617, 55-09618, 55-09683, 55-10011, 55-10360, 55-10361, 55-10614, 55-11599, 63-63304, 63-66687, 63-67691, 63-67736, 63-67180, 63-73362, 63-67180, 63-73361, 63-71587, 11-12330, 63-70375, 51-90346, 55-13788, 55-13787, 55-13785, 55-13789, 55-13786, 55-13903, 55-13946, 55-13947, 55-13949, 55-13947, 55-13951, 55-14175, 55-14172, 55-14187, 55-14188, 51-87213, 55-14395, 55-14410, 55-14409, 51-888032, 55-14866, 55-14888, 51-88306, 51-88548, 51-88870, 51-89881, 11-11252, 51-89766, 51-89882, 51-89883, 55-15760, 55-15761, 51-91118, 51-91119, 51-91460, 51-88548, 55-12193, 55-12326, 55-10408, 51-91756, 51-92318, 55-16701, 51-93926, 51-93201, 51-93487, 51-95837, 51-95140, 51-96151, 51-96511, 51-96450, 51-96575, 51-96572, 51-96573, 51-96570, 51-96571, 51-96574, 51-97056, 55-17931, 51-97313, 51-97311, 51-97312, 51-97316, 51-97641, 51-97647, 51-97644, 51-88746, 51-88751, 51-96151, 51-91527; 11-11252, 51-99873, 51-99874, 51-99051, 51-97822, 51-97824, 55-13403, 56-02588, 56-02269, HCTIMP_S162368.42656, HCTIMP_S162368.42673, LT-00838808, LT-0066086, 51-95205, 51-95207, 56-03326, 56-03771, 56-04442, 56-04676, 56-04677, 56-05232, 56-05342, 56-05341, 56-05340, 56-05458, 56-05909, 56-05984, 56-06240, 56-06239, 56-06691, 56-02588, 56-02972, 51-3973255, 56-09348, 56-09421, 56-09104, 51-77099, 56-09584, 56-09643, 56-10032, 56-10108, 56-10063, 56-10968, 56-10969, 10-17958, 56-10063, 10-17958, 56-11192, 56-11193, 11-11252, 56-11644, 56-08706, 51-99160, 56-01890, 51-97823, 56-00201, 56-00597, 56-02024, 56-91527, 56-11432, 56-11080, 56-14002, 56-14003, 56-11975, 56-13873, 56-15386, 56-16087, 56-16086, 56-16058, 56-16278, 56-16503, 56-16480, 56-16623, 56-16624, 56-16562, 56-16561, 56-16897, 56-16704, 56-17241, 56-17090, 56-17172, 56-17283, 56-17354, 56-17573, 56-17627, 56-17709, 56-17748, 56-17960, 56-18246, 56-18246, 56-18913, 56-19733, 56-19862, 56-16704, 56-19865, 56-13997, 1501261155, 56-17431, 56-18633, 56-18744, 56-19069, 9303251204, 56-19416, 56-19558, 56-19594, 56-19733, 56-19860, 56-20090, 55-22074, 55-22077, 11-12320, 56-21986, 56-21053, 1401261142, 1401261129, 56-21986, 2701261041, 10-17958

הוראות בטיחות

1. להתקנה על ידי אנשי שירות מוסמכים בלבד.
 2. אין לבצע שינויים כלשהם במוצר זה. לשינויים אלו יכולה להיות השפעה שלילית על ביצועי המוצר, בטיחותו ועמידותו ובנוסף, יש בהם כדי לחרוג מתנאי האחריות.
- חל איסור לבצע פעולות במכשיר שיש בהן כדי לשנות את תכונותיו האלחוטיות של המכשיר, ובכלל זה שינויי תוכנה, החלפת אנטנה מקוריית או הוספת אפישורת לחיבור לאנטנה חיצונית, בלא קבלת אישור משרד התקשורת, בשל החשש להפרעות אלחוטיות.
- אסור להחליף את האנטנה המקורית של המכשיר ולא לעשות בו כל שינוי טכני אחר.

Jamaica

This product contains a Type Approved Module by Jamaica:

SMA Equipment Identifier:

FR5CUEC, RS5.3, RS5.5MQBS01, TSSRE4Uf, TSSSG4G5b, WPC003-1, Medium 5C_21, TSSRE4Td, FPK8 IMMO5D, CB2JCIBUSHL4, LTE-MBC-NAR2, TLVHM3IU-W, LTE-MBC-NAR2, LTE-MBC-NARTSSSG4G4, TSSTS, TLAHW3IU-W, FS14T and FS14TK, WCH-186, WCH-185, WCH-183, 17101031, CONBOX-HIGH, MQB3 OI, MEDIUM 5C & COLOUR 5C, 17101023, 17101022, 17101032, 17101043, 17101041, 18020534, ARS5-B, 18020534, TSSRE4A, VK2, VW MIB2 Entry, MIB GLOBAL STANDARD PLUS, RS4, 18020534, 5WK50257/254/252/250/248/40398036/40406557/4038279, FS94, FS09, VW India 2.0 Low Radio, VW MIB Regio, F5CP42, MQBS01, WPC003-5, BCM37WBL, WPC003-1, MQBS01, BR22, FPK815DTR2, TLVUM3IU-W, TLVUW3IU-W, FS195, FS191S, TLVUW3IU-W, TLVUM3IU-W, WCH-304, UWBtr22, UWBBL22, SCB, MIB3 OI, MIB3 OI VR-E, MIB3GP, HFA30, MIB3 EI GP MQBevo, TKCMOD11000W, WPC003-1, I25U, HFA31, NBOG1RS53, NBOG1RS55, CB2JCIBUSHL4

Hashemite Kingdom of Jordan

TRC no.:

TRC/LPD/2010/91, TRC/LPD/2014/9, TRC/LPD/2014/186, TRC/LPD/2014/214, TRC/LPD/2014/241, TRC/LPD/2014/248, TRC/LPD/2014/258, TRC/LPD/2014/274, TRC/LPD/2015/387, TRC/LPD/2016/170, TRC/LPD/2016/215, TRC/LPD/2016/216, TRC/LPD/2016/252, TRC/LPD/2016/353, TRC/LPD/2016/478, TRC/LPD/2016/538, TRC/LPD/2016/584, TRC/LPD/2016/591, TRC/LPD/2017/63, TRC/LPD/2017/254, TRC/LPD/2018/1, TRC/LPD/2018/128, TRC/LPD/2018/162, TRC/LPD/2018/193, TRC/LPD/2018/228, TRC/LPD/2018/272, TRC/LPD/2018/274, TRC/LPD/2018/381, TRC/LPD/2018/399, TRC/LPD/2018/489, TRC/LPD/2018/528, TRC/LPD/2018/529, TRC/LPD/2019/67, TRC/LPD/2019/152, TRC/LPD/2019/153, TRC/LPD/2019/155, TRC/LPD/2019/227, TRC/LPD/2019/233, TRC/LPD/2019/234, TRC/LPD/2021/215, TRC/9257/2021.

TRC/SS/2010/48, TRC/SS/2014/127, TRC/SS/2015/221, TRC/SS/2015/222, TRC/SS/2016/476, TRC/SS/2019/212, TRC/31/7615/2020, TRC/31/5862/2022, TRC/32/6684/2023, TRC/31/11434/2023, TRC/31/11517/2023, TRC/34/6696/2023, TRC/31/11516/2023, TRC/31/9121/2021, TRC/34/12409/2023, TRC/36/7651/2022, TRC/31/712/2020, TRC/34/13027/2023, TRC/32/7603/2020, TRC/32/7604/2020, TRC/34/10235/2022, TRC/34/9541/2022, TRC/34/9710/2022, TRC/34/14044/2024, TRC/35/1922/2024, TRC/34/13799/2024, TRC/34/13604/2024, TRC/34/11842/2023, TRC/34/11841/2023, TRC/34/12409/2023, TRC/34/8847/2024, TRC/19/15439/2024.

TRC No.: T/4/11/11/... , 0354, 1200, 2394, , 2950, 3338, 3339, 3474, 3502, 3506, 3512, 3641, 3680, 3681, , 4215, 4350, 4352, 4387, 4549, 4554, 4555, 5616, 5621, 5649, 5653, 5896, 5898, 5974, 5976, 5977, 6082, 6435, 7192, 7216, 7218, 7716, 7777, 8007, 8163, 8164, 8205, 8225, 8226, 8227, 8230, 8278, 8281, , 8677, 8680, 8793, 8910, 9184, 9229, 9236, 9351, 9352, 9585, 9851, 10124, 10354, 10488, 10752, 10753, 11026, 11078, 12260, 194200, 1199, 2950, 3512, 4215, 5397, 5739, 8102, 9215, 9217, 9

32,2517,2612,2609,2608, 258, 382, 9177, 9343, 976, 1142, 1417, 1626, 1748, 2498, 2855, 2854, 2912, 3097, 3196, 3248, 3391, 3392, 3658, 3731, 4537, 3820, 4099, 4087, 4100, 4423, 4422, 4586, 5159, 5200, 4099, 5318, 5365, 5874, 5872, 5875, 7103, 7042, 7068, 7067, 7045, 7710, 7814, 11932, 4257, 1857, 1088, 5687, 1916, 4570, 4902, 5159, 5157, 6685, 7648, 8711, 9271, 11021, 11044, 11514, 625, 1465, 1693, 1947

Republic of Cameroon

AGENCE DE REGULATION DES TELECOMMUNICATIONS CAMEROUN

HOMOLOGATION D'EQUIPEMENT:

106/ART/DG/DT/SDNSEA/SNH/CA, 125/ART/DG/DT/SDNSEA/SNH/CA, 137/ART/DG/DT/SDNA/SNH/CA1, 139/ART/DG/DT/SDNA/SNH/CA1, 152/ART/DG/DT/SDNA/SNH/CA2, 167/ART/DG/DT/SDNA/SNH/CA3, 170/ART/DG/DT/SDNA/SNH/CA2, 172/ART/DG/DT/SDNA/SNH/CA2, 271/ART/DG/DT/SDNA/SNH/CA2, 273/ART/DG/DT/SDNA/SNH/CA2, 287/ART/DG/DT/SDNA/SNH/CA2, 293/ART/DG/DT/SDNA/SNH, 301/ART/DG/DT/SDNSEA/SNH/CA, 305/ART/DG/DT/SDNA/SNH/CA1, 309/ART/DG/DT/SDNA/SNH/CA1, 318/ART/DG/DT/SDNA/SNH/CA1, 428/ART/DG/DT/SDNA/SNH/CA1, 458/ART/DG/DT/SDNSEA/SNH, 459/ART/DG/DT/SDNSEA/SNH, 465/ART/DG/DT/SDNA/SNH, 469/ART/DG/DT/SDNA/SNH/CA2, 475/ART/DG/DT/SDNA/SNH/CA2, 581/ART/DG/DT/SDNA/SNH/CA2, 616/ART/DG/DT/SDNA/SNH/CA2, 628/ART/DG/DT/SDNA/SNH/CA1, 631/ART/DG/DT/SDNA/SNH/CA1, 720/ART/DG/DT/SDNA/SNH/CA2, 722/ART/DG/DT/SDNA/SNH/CA2, 726/ART/DG/DT/SDNA/SNH/CA2, 734/ART/DG/DT/SDNA/SNH/CA2, 778/ART/DG/DT/SDNA/SNH/CA1, 788/ART/DG/DT/SDNSEA/SNH/CA, 851/ART/DG/DT/SDNA/SNH/CA2, 856/ART/DG/DT/SDNA/SNH/CA2, 870/ART/DG/DT/SDNA/SNH/CA2, 1129/ART/DG/DT/SDNSEA/SNH/CA, 1151/ART/DG/DT/SDNSEA/SNH, 1789/ART/DG/DT/SDNA/SNH, 1150/ART/DG/DT/SDNSEA/SNH, 1152/ART/DG/DT/SDNSEA/SNH, 135/ART/DG/DT/SDNSEA/SNH, 289/ART/DG/DT/SDNSEA/SNH, 295/ART/DG/DT/SDNSEA/SNH, 492/ART/DG/DT/SDNSEA/SNH, 655/ART/DG/DT/SDNSEA/SNH, 656/ART/DG/DT/SDNSEA/SNH, 663/ART/DG/DT/SDNSEA/SNH, 2784/ART/DG/DT/SDNSEA/SNH, 834/ART/DG/DT/SDNSEA/SNH, 837/ART/DG/DT/SDNSEA/SNH, 941/ART/DG/DT/SDNSEA/SNH, 36/ART/DG/DT/SDNSEA/SNH, 79/ART/DG/DT/SDNSEA/SNH, 78/ART/DG/DT/SDN/SEA/SNH, 333/ART/DG/DT/SDN/SEA/SNH/CA, 442/ART/DG/DT/SDN/SEA/SNH/CA, 113/ART/DG/DT/SDN/SEA/SNH/CA, 111/ART/DG/DT/SDN/SEA/SNH/CA, 653/ART/DG/DT/SDNSEA/SNH, 974/ART/DG/DT/SDNSEA/SNH, 58/ART/DG/DT/SDNSEA/SNH, 856/ART/DG/DT/SDNSEA/SNH/CA, 131/ART/DG/DT/SDNSEA/SNH/CA, 263/ART/DG/DT/SDNSEA/SNH/CA, 549/ART/DG/DT/SDNA/SNH, 545/ART/DG/DT/SDNA/SNH, 665/ART/DG/DT/SDNSEA/SNH, 469/ART/DG/DT/SDNSEA/SNH/CA, 791/ART/DG/DT/SDNSEA/SNH, 931/ART/DG/DT/SDNSEA/SNH, 923/ART/DG/DT/SDNSEA/SNH, 925/ART/DG/DT/SDNSEA/SNH, 153/ART/DG/DT/SDNSEA/SNH/CA, 205/ART/DG/DT/SDNSEA/SNH, 232/ART/DG/DT/SDNSEA/SNH, 803/ART/DG/DT/SDNSEA/SNH, 495/ART/DG/DT/SDNSEA, 336/ART/DG/DT/SDNSEA/SNH, 16/ART/DG/DT/SDNSEA/SNH

Republic of Malawi

MACRA



Type approval number:

MLW/MACRA/TA/11/2021/01173, MLW/MACRA/TA/11/2021/01174, MLW/MACRA/TA/02/2022/01227, MLW/MACRA/TA/03/2022/01242, MLW/MACRA/TA/03/2022/01243, MLW/MACRA/TA/08/2022/01311, MLW/MACRA/TA/02/2023/01414, MLW/MACRA/TA/06/2023/01460, MLW/MACRA/TA/07/2023/01462, MLW/MACRA/TA/07/2023/01465, MLW/MACRA/TA/09/2023/01509, MLW/MACRA/TA/10/2023/01526, MLW/MACRA/TA/2024/01579, MLW/MACRA/TA/07/2025/01785, MLW/MACRA/TA/07/2025/01788, MLW/MACRA/TA/07/2026/02143

Malaysia



CIDF15000490, CIDF15000578, CIDF17000143, MRR14F, AR54-B, MIB3 0I

RAAT/44A/0219/S(19-0487), RAAU/05C/0415/S(14-3022), RAAU/33C/1015/S(15-0535), RAAU/35C/1115/S(15-0536), RAAU/40C/1215/S(15-4937), RAAU/48C/0716/S(16-2025), RAAU/57A/0111/S(10-2112), RAAU/84A/0618/S(18-2241), RAAU/85A/0618/S(18-2242), RAAU/86A/0618/S(18-2378), RAAU/87A/0718/S(18-2596), RAAU/92A/1218/S(18-4731), RAAU/98A/0620/S(20-2103), RAFC/18A/0618/S(18-2470), RALM/22A/0315/S(15-0480), RALM/35A/0716/S(16-2324), RALM/43B/0221/S(21-0619), RALM/66A/0618/S(18-2468), RALM/67A/0618/S(18-2474), RALM/68A/0618/S(18-2473), RALM/69A/1018/S(18-3829), RALM/77A/0219/S(19-0174), RANI/26C/1215/S(15-4798), , , RANI/72B/0215/S(14-3024), RBEF/04A/0317/S(17-0584), RBEF/30A/0919/S(19-3760), RCCT/61D/0719/S(19-2714), , , RDCC/72A/0518/S(18-1697), RDDK/02B/0419/S(19-1401), RDDK/08A/0416/S(16-1233), RDDK/08B/0416/S(16-1233), RDDK/17A/0816/S(16-2023), RDDK/22A/1016/S(16-3306), , RDDK/68A/0418/S(18-1521), RDDK/69B/1220/S(20-5452), RDDS/27A/0319/S(19-1029), RDFX/09A/0821/S(21-4059), RDFX/10A/0921/S(21-4061), RDFX/11A/0921/S(21-4060), RFCL/09A/0218/S(18-0609), RFCL/13A/0618/S(18-2379), RFCL/14A/0618/S(18-2543), RFCL/15A/0718/S(18-2544), RFCL/18A/0718/S(18-2529), RFCL/19A/0718/S(18-2545), RFCL/20A/0718/S(18-2718), RFCL/21A/0718/S(18-2717), RFCL/22A/0818/S(18-3109), RFCL/23A/0818/S(18-3153), RFCL/24A/0818/S(18-3152), RFCL/26A/0918/S(18-3810), RFCL/27A/0918/S(18-3812), RFCL/28A/1018/S(18-3977), RFCL/30A/1018/S(18-4129), RFCL/31A/1018/S(18-3976), RFCL/33A/0619/S(19-2422), RFCL/34A/0619/S(19-2421), RFCL/35A/0719/S(19-2874), RFCL/41A/0220/S(20-0390), RFCL/42A/0220/S(20-0391), RFCL/44A/0320/S(20-1385), RFCP/36A/0321/S(21-1381), RFGF/05A/0519/S(19-2090), RGBZ/01A/0318/S(18-0918), RGBZ/03A/0320/S(20-1253), RGEZ/25A/0920/S(20-3544), RGEZ/31A/0421/S(21-1529), RGEZ/36A/0521/S(21-2216), RGIG/01A/0220/S(20-0593), RGIG/02A/0220/S(20-0591), RGLA/06A/1220/S(20-5384), RGNU/03A/0221/S(21-0560), RCCT/02G/1021/S(21-4512), RAQP/73A/1121/S(21-5209), RAQP/76A/1121/S(21-5310), RAQP/75A/1121/S(21-5309), RRCCT/19G/1121/S(21-4614), RFGF/05A/0519/S(19-2090), RALM/77A/0219/S(19-0174), RALM/54B/1221/

S(21-5945), RALM/34A/0616/S(16-0899), RGLN/26A/0122/
S(22-0336), RAQP/77A/0222/S(22-0908), RGEZ/45A/0322/
S(22-1385), RAVG/39U/0616/S(16-1865), RCCT/46B/0317/
S(17-0740), RCCT/47B/0317/S(17-0739), RCCT/64B/0517/S(17-0741),
RAAU/40C/1215/S(15-4937), RAAU/57A/0111/S(10-2112), RAVG/39U/
0616/S(16-1865), RDDK/23A/0916/S(16-3288), RAQP/84A/0822/
S(22-3841), RBEF/30A/0919/S(19-3760), RAQP/84A/0922/S(22-4095),
RAQP/88A/1022/S(22-4485), RALM/75B/1122/S(22-5510), RALM/74B/
1122/S(22-5508), RALM/22A/0315/S(15-0480), RAQP/84A/0223/
S(23-0548), RGLA/06A/1220/S(20-5384), RGIH/67A/0522/S(22-2480),
RALM/90B/0323/S(23-0831), RALM/89B/0323/S(23-0830), RALM/90B/
0323/S(23-0831), RFPC/23A/0323/S(23-1490), RALM/44A/0517/
S(17-1383) RGLN/01A/0620/S(20-2413), RGM/20B/0820/S(20-3382),
RALM/21B/0820/S(20-3381), RGLN/46A/0523/S(23-2144), RFCL/83A/
0623/S(23-2566), RFCL/84A/0623/S(23-2507), RFCL/85A/0623/
S(23-2508), RFCL/86A/0623/S(23-2693), RFCL/94A/0623/S(23-2789),
RFCL/87A/0623/S(23-2595), RFCL/88A/0623/S(23-2694), RFCL/89A/
0623/S(23-2684), RFCL/94A/0623/S(23-2789), RFCL/95A/0623/
S(23-2791), RFCL/91A/0623/S(23-2786), RFCL/92A/0623/S(23-25787),
RFCL/93A/0623/S(23-2788), RFCL/04C/0623/S(23-2911), RFCL/97A/
0723/S(23-3079), RFCL/96A/0723/S(23-3078), RFLC/99A/0723/
S(23-3077), RFCL/98A/0723/S(23-3076), RALM/33B/1120/S(20-4706),
RAQP/07B/0823/S(23-3721), RAQP/06B/0823/S(23-3720), RDDK/75C/
0223/S(23-0474), RDDK/74C/0223/S(23-0472), RGGV/20A/1222/
S(22-5600), RGLG/38A/1023/S(23-4773), RGMK/39A/1023/S(23-4774),
RGGK/40A/1023/S(23-4775), RGSC/06A/0723/S(23-3045), RGSC/07A/
0723/S(23-3046), RFFK/06A/0522/S(22-2423), RGWQ/32A/0324/
S(24-0892), RDDK/68A/0418/S(18-1521), RFBY/29A/0524/S(24-2032),
RFBY/30A/0524/S(24-2033), RFBY/32A/0624/S(24-2578), RDDK/83A/
1018/S(18-4152), RDDK/83A/1018/S(18-4153), RGEZ/72A/0824/
S(24-3502), RDDK/62D/1024/S(24-4684), RAQP/75A/1121/S(21-5309),
RFPC/45B/0225/S(25-0632), RGZM/03A/0225/S(25-0803), RGLN/66A/
0325/S(25-1051), RALM/59C/0325/S(25-1039), RFLC/02B/0419/
S(19-1401), RDDK/08A/0416/S(16-1223), RGGK/41A/0425/S(25-1607),
RDDK/92D/0525/S(25-2345), RFPC/57B/0525/S(25-0223), RFPC/57B/
0525/S(25-0224), RAVG/39U/0616/S(16-1865), RGLA/04A/0920/
S(20-3545), RGEZ/25A/0920/S(20-3544), RDDK/19E/0825/S(25-4312),
RAQP/84A/0822/S(22-3841), RAQP/61B/0925/S(25-4808), RAQP/65B/
0925/S(25-4987), RGZM/05A/0925/S(25-5188), RAQP/67B/1025/
S(25-5127), RGZK/09A/0126/S(25-7031), RALM/39B/0121/S(21-0517),
RALM/43B/0221/S(21-0619), RALM/98C/0126/S(26-0274), RALM/42B/
0221/S(21-0574), RGZK/10A/0226/S(26-0386), RGNU/03A/0221/
S(21-0560), RALM/36B/1220/S(20-5288), RIQJ/26A/0226/S(26-0264).

MR 9904ANRT2014_13.11.2024, MR 11030ANRT2015_04.11.2015,
MR 11554ANRT2016_15.03.2016, MR 12089ANRT2016_15.06.2016,
MR 12123ANRT2016_22.06.2016, MR 12372ANRT2016_16.08.2016,
MR 12623ANRT2016_11.10.2016, MR 12755ANRT2016_07.11.2016,
MR 12756ANRT2016_07.11.2016, MR 12901ANRT2016_30.11.2016,
MR 13217ANRT2017_27.01.2017, MR 13255ANRT2017_09.02.2017,
MR 13576ANRT2017_20.03.2017, MR 13772ANRT2017_13.04.2017,
MR 13774ANRT2017_13.04.2017, MR 13851ANRT2017_03.05.2017,
MR 13892ANRT2017_03.05.2017, MR 13900ANRT2017_04.05.2017,
MR 14830ANRT2017_28.09.2017, MR 15171ANRT2017_22.11.2017,
MR 15669ANRT2018_31.01.2018, MR 15674ANRT2018_31.01.2018,
MR 15675ANRT2018_31.01.2018, MR 15925ANRT2018_27.02.2018,
MR 16263ANRT2018_06.04.2018, MR 16606ANRT2018_17.05.2018,
MR 16657ANRT2018_23.05.2018, MR 16726ANRT2018_30.05.2018,
MR 16794ANRT2018_05.06.2018, MR 16860ANRT2018_18.06.2018,
MR 16861ANRT2018_18.06.2018, MR 16905ANRT2018_21.06.2018,
MR 16906ANRT2018_21.06.2018, MR 16907ANRT2018_21.06.2018,
MR 16908ANRT2018_21.06.2018, MR 17015ANRT2018_03.07.2018,
MR 17016ANRT2018_03.07.2018, MR 17079ANRT2018_11.07.2018,
MR 17080ANRT2018_11.07.2018, MR 17201ANRT2018_06.08.2018,
MR 17202ANRT2018_06.08.2018, MR 17203ANRT2018_06.08.2018,
MR 17204ANRT2018_06.08.2018, MR 17504ANRT2018_14.09.2018,
MR 17505ANRT2018_14.09.2018, MR 17528ANRT2018_20.09.2018,
MR 17576ANRT2018_26.09.2018, MR 17678ANRT2018_11.10.2018,
MR 17679ANRT2018_11.10.2018, MR 18103ANRT2018_30.11.2018,
MR 18334ANRT2018_21.12.2018, MR 18335ANRT2018_21.12.2018,
MR 18615ANRT2019_21.01.2019, MR 18736ANRT2019_04.02.2019,
MR 18928ANRT2019_25.02.2019, MR 19106ANRT2019_14.03.2019,
MR 19108ANRT2019_14.03.2019, MR 19331ANRT2019_09.04.2019,
MR 19338ANRT2019_09.04.2019, MR 19339ANRT2019_09.04.2019,
MR 19505ANRT2019_22.04.2019, MR 19520ANRT2019_23.04.2019,
MR 19767ANRT2019_15.05.2019, MR 19768ANRT2019_15.05.2019,
MR 19769ANRT2019_15.05.2019, MR 20859ANRT2019_11.09.2019,
MR 20901ANRT2019_13.09.2019, MR 20902ANRT2019_13.09.2019,
MR 20944ANRT2019_19.09.2019, MR 21472ANRT2019_26.11.2019,
MR 21473ANRT2019_28.11.2019, MR 21807ANRT2019_23.12.2019,
MR 22495ANRT2020_26.02.2020, MR 23231ANRT2019_25.05.2020,
MR 23405ANRT2020_16.03.2020, MR 24001ANRT2020_13.05.2020,
MR 24106ANRT2020_20.05.2020, MR 25982ANRT2020_14.10.2020,
MR 26081ANRT2020_22.10.2020, MR 26333ANRT2020_12.11.2020,
MR 27808ANRT2021_13.03.2021, MR 30377ANRT2021_14.10.2021,
MR 31268ANRT2022_04.01.2022, MR 29628ANRT2021_02.08.2021, MR
30406ANRT2021_24.10.2021, MR 30494ANRT2021_28.10.2021, MR 305
29ANRT2021_01.11.2021, MR 30528ANRT2021_01.11.2021, MR 31458A
NRT2022_24.01.2022, MR 25075ANRT2020_10.05.2022,
MR 33226ANRT2022_01.06.2022, MR 30377ANRT2021_14.10.2021,
MR 30377ANRT2021_26.10.2022, MR 8106ANRT2013_26.10.2022,
MR 9186ANRT2014_04.04.2024, MR 9668ANRT2014_26.10.2022,
MR 11264ANRT2016_27.10.2022, MR 17528ANRT2018_27.10.2022,
MR 9126ANRT2014_27.10.2022, MR 35384ANRT2022_21.11.2022,
MR 35382ANRT2022_21.11.2022, MR 35387ANRT2022_21.11.2022,
MR 35393ANRT2022_21.11.2022, MR 36711ANRT2023_10.02.2023,
MR 25982ANRT2020_14.10.2020, MR 31772ANRT2020_17.02.2022,
MR 35739ANRT2022_12.12.2022, MR 36711ANRT2020_10.02.2023,
MR 31772ANRT2020_03.04.2023, MR 37224ANRT2023_23.06.2023,
MR 31774ANRT2017_10.08.2023, MR 12122ANRT2016_10.08.2023,
MR 12123ANRT2016_10.08.2023, MR 35351ANRT2022_17.11.2022,
MR 35350ANRT2022_17.11.2022, MR 37357ANRT2023_17.03.2023,

Kingdom of Morocco
AGREE PAR L'ANRT MAROC



Abb. 1

Numéro d'agrément_Date d'agrément

MR 5371ANRT2010_05.12.2019, MR 5835ANRT2010_28.08.2020,
MR 9107ANRT2014_18.03.2014, MR 9778ANRT2014_08.08.2024,

MR 37442ANRT2023_22.03.2023, MR 39161ANRT2023_13.07.2023, MR 490ANRT2024_05.02.2024, MR 1286ANRT2024_29.03.2024, MR 2040ANRT2024_24.02.2024, MR 2609ANRT2025_13.05.2025, MR 9778ANRT2014_08.08.2024, MR 9904ANRT2014_13.11.2024, MR 5805ANRT2024_26.12.2024, MR 3921ANRT2025_21.07.2025, MR 4090ANRT2025_28.07.2025, MR 4641ANRT2025_08.09.2025, MR 11264ANRT2016_09.12.2025 .

Islamic Republic of Mauritania
AGREE PAR L'ARE MAURITANIE

Numéro d'agrément_Date d'agrément:

, 0598/ARE/2018_13.12.2018, 0630/ARE/2019_25.02.2019, 0647/ARE/2019_30.04.2019, 0649/ARE/2019_30.04.2019, 0650/ARE/2019_30.04.2019, 0664/ARE/2019_27.05.2019, 0665/ARE/2019_27.05.2019, 0667/ARE/2019_27.05.2019, 0712/ARE/2018_04.11.2019, 0713/ARE/2018_04.11.2019, 0742/ARE/2020_20.01.2020, 0796/ARE/2020_11.05.2020, 0839/ARE/2020_21.09.2020, 0840/ARE/2020_21.09.2020, 0874/ARE/2020_26.11.2020, 0971/ARE/2021_20.07.2021, 0979/ARE/2021_09.08.2021, 1128/ARE/2021_27.06.2022, 1127/ARE/2021_27.06.2022, 1173/ARE/2022_17.10.2022, 1120/ARE/2022_24.05.2022, 232/ARE/2023_13.02.2023, 1212/ARE/2022_22.12.2022, 1251/ARE/2023_16.03.2023, 1252/ARE/2023_20.03.2023, 1263/ARE/2023_17.04.2023, 1267/ARE/2023_17.05.2023, 1269/ARE/2023_17.05.2023, 1270/ARE/2023_17.05.2023, 1296/ARE/2023_13.06.2023, 1297/ARE/2023_13.06.2023, 1303/ARE/2023_03.07.2023, 1306/ARE/2023_03.07.2023, 1304/ARE/2023_03.07.2023, 1303/ARE/2023_03.07.2023, 1305/ARE/2023_03.07.2023, 1218/ARE/2023_02.02.2023, 1219/ARE/2023_02.02.2023, 1329/ARE/2023_22.08.2023, 1334/ARE/2023_04.09.2023, 1332/ARE/2023_04.09.2023, 1356/ARE/2023_02.10.2023, 1408/ARE/2024_23.01.2024, 1439/ARE/2024_27.03.2024, 1606/ARE/2025_11.03.2025

Mexico



NYCE:, NYC-CEDT1456-21, , NYC-CEDT0106-23, NYC-CEDT2073-23, NYC-2402CT0118-24, NYC-2402CT0204-24, NYC-2402CT0207-24, NYC-2402CT0305-24, NYC-CEDT0587-24, NYC-CEDT0621-24, NYC-CEDT0634-24, NYC-CEDT1118-24, NYC-CEDT1119-24, NYC-CEDT1782-24, NYC-2402COE19421, NYC-2402COE20218, NYC-2402COE20285, NYC-CEDT0327-25, NYC-2502CT0187, NYC-2502CT0181-01A, NYC-CEDT0910-25, NYC-CEDT1175-25, NYC-CEDT1618-25, NYC-2502COE15682, NYC-2502COE19479, NYC-CEDT0128-26, NYC-CEDT0213-26, NYC-CEDT0315-26

ANCE:ANC2101C00017489,ANC2201C00003403,ANC2201C00004471

IFETEL:

IFT/223/UCS/DG-AUSE/0311/2018, IFT-008-2015, IFT/223/UCS/DG-AUSE/10559/2021, IFT/223/UCS/DG-AUSE/9797/2021, IFT/223/UCS/DG-AUSE/9793/2021, IFT/223/UCS/DG-AUSE/9791/2021, IFT/223/UCS/DG-AUSE/9792/2021, IFT/223/UCS/DG-AUSE/9796/2021, IFT/223/UCS/DG-AUSE/9788/2021, IFT/223/UCS/DG-AUSE/0029/2021, IFT/223/UCS/DG-AUSE/7577/2021, IFT/223/UCS/DG-AUSE/6918/2022, IFT/223/UCS/DG-AUSE/6915/2022, IFT/223/UCS/DG-AUSE/1911/2022, IFT/223/UCS/DG-AUSE/2294/2022, IFT/223/UCS/DG-AUSE/2516/2022, IFT/223/UCS/DG-AUSE/1766/2022, IFT/223/UCS/DG-AUSE/3659/2022, IFT/223/UCS/DG-AUSE/3672/2022, IFT/223/UCS/DG-AUSE/4769/2022, IFT/223/UCS/DG-AUSE/1540/2022, IFT/223/UCS/DG-AUSE/3129/2022, IFT/223/UCS/DG-AUSE/4898/2022, IFT/223/UCS/DG-AUSE/4897/2022, IFT/223/UCS/DG-AUSE/4551/2022, IFT/223/UCS/DG-AUSE/xxxx/2022, , IFT/223/UCS/1365/2023, IFT/223/UCS/1940/2023, IFT/223/UCS/2740/2023, IFT/223/UCS/3554/2023, IFT/223/UCS/3942/2023, IFT/223/UCS/3950/2023, IFT/223/UCS/1175/2023, IFT/223/UCS/1174/2023, IFT/223/UCS/DG-AUSE/7603/2020, IFT/223/UCS/DG-AUSE/2408/2021, IFT/223/UCS/7549/2023, IFT/223/UCS/8987/2024, IFT/223/UCS/9014/2024, IFT/223/UCS/9501/2024, IFT/223/UCS/853/2025, IFT/223/UCS/DG-AUSE/1759/2025, IFT/223/UCS/2973/2025, IFT/223/UCS/3635/2025, IFT/223/UCS/3636/2025, IFT/223/UCS/3555/2025, IFT/223/UCS/4271/2025, IFT/223/UCS/5681/2025, IFT/223/UCS/7129/2025

RCPVVW21-4222, RCPAPR31-2005, RCPBOBR21-0911, RCPBOFR18-1885, RCPBOLR09-0828, RCPBOLR16-0518, RCPBOMR12-1538, RCPBOMR14-0766, RCPBOMR14-0922, RCPBOMR17-0598, RCPBOMQ19-0594, RCPCO-AR18-1800, RCPGEAD16-1700, RCPHAMM10-0514, RCPHEBS14-0180, RCPHEBC18-2099, RCPHEFS19-1702, RCPHEFS20-1469, RCPHERS19-1678, RCPHERS21-4334, RCPHERS21-4335RCPGEAD16-1700, RCPGECB14-0464, RCPGLG16-0952, RCPGLM19-1163, RCPVIVW20-0478, RCPVOHT13-1485, RCPVOMI15-0115, RCPVWFS16-0693, RCPVWL414-0775, RCPVWL414-0775-A1, RCPVWL617-0023, RCPVWM17-0707, RCPVWM17-0902, RCPVWM18-2151, RCPVWM18-2169, RCPVWM14-0755, RCPVWM14-1819, RCPVWM14-1819, RCPVWM14-1820, RCPVWM15-0640, NYC-2002COE22330, RCPVWM16-0590, RCPVWM16-1445, RCPVWMM17-1053, RCPVWVW17-0714, RCPVWVW17-0714-A1, RLVBHTS19-1995, RVLBOLR14-1873, RLVCO1820-0821, RLVCO-AR15-0008, RLVCOBC16-1823, RLVCO1820-0821, RLVCOFS18-2029, RLVCOFS18-2030, RLVDER316-1666, RLVDER316-2005, RLVHEO119-0720, RLVHEBC15-0293, RLVHEBC16-0682, RLVHEFS13-1688, RLVHEFS13-1690, RLVHEFS14-1515, RLVHEFS18-1288, RLVHEFS18-1565, RLVHEFS19-0647, RLVHEFS19-1298, RLVHEFS20-0533, RLVHEFS20-1335, RLVHEFS20-1336, RLVHEFS20-1420, RLVHEL11-1185, RLVHEMQ19-1757, RLVHEMQ19-1758, RLVHEMW19-1757, RLVHERS17-0286, RLVHUHU19-1065, RLVHUTS20-1781, RLVMABN18-1512, RLVMABN18-1512-A1, RLVMMAMQ18-0363, RLVMMAMQ20-2464, RLVVENB20-1419, RLVVICO19-1023, RLVVIFP20-1412, RLVVICO18-0155, RLVVIME19-1022, RLVVIME19-1023, RLVVIME20-2934, RLVVWFS17-2122, RLVVWFS17-2122-A1, RLVVW1718-1092, RLVVW1718-1169, RLVVW1718-1170, RLVVW1718-1171, RLVVW1718-1314, RLVVW1718-1315, RLVVW1718-1316, RLVVW1718-1317, RLVVW1718-1507, RLVVW1718-1508, RLVVW1718-1509, RLVVW1718-1517, RLVVW1718-1518, RLVVW1718-1519, RLVVW1718-1567,

RLVVW1718-1568, RLVVW1718-1789, RLVVW1718-1790, RLVVW1718-1928, RLVVW1718-1929, RLVVW1719-1795, RLVVW1818-1248, RLVVW1818-1249, RLVVW1818-1258, RLVVW1819-0009, RLVVW1819-0023, RTIAUCB18-0153, RTIAU-M14-1863, RTILECO19-1805, RTILECO21-2443, RTILGTL19-0483, RTILGTL19-1617, RTILGTL20-727, RTIMOLT20-1047, RTIIVV-CO19-1185, RCPVWMI22-1384, RLVNAMQ22-3409, VOVWMI23-13062, VOVWMI23-13050, RCPVWMI22-1384, VOVWTK23-30067, VOVWCP23-19309, SYMOWC23-01151, ROVIHF24-02919, ULM-NOM-16943, VOAPMI24-05677, VOVWMI24-05362, VOVW-MI24-05354, VOJOMI24-09641, VOJOMI24-10742, TEHUFL24-14072, TEHUFL24-14071, RLVCOAR15-0008, VOHUNF24-22616-0008, VOHERS25-33967, VOHE0125-33965, RCPHERS21-4334, VRCPHERS21-4335.

La operación de este equipo está sujeta a las siguientes dos condiciones:

- (1) es posible que este equipo o dispositivo no cause interferencia perjudicial y
- (2) este equipo o dispositivo debe aceptar cualquier interferencia, incluyendo la que pueda causar su operación no deseada.

Federal Republic of Nigeria

Connection and use of this communications equipment is permitted by the Nigerian Communications Commission.



NCC/TSNi/WN/TA/CERT/: 0043/2011, 0679/2015, 0884/2015, 0922/2015, 0923/2015, 0947/2016, 1071/2016, 1247/2016, 1454/2017, 1567/2017, 1571/2017, 1650/2017, 1691/2017, 1692/2017, 2061/2018, 2062/2018, 2236/2018, 2332/2018, 2333/2018, 2334/2018, 2335/2018, 2338/2018, 2339/2018, 2340/2018, 2383/2018, 2384/2018, 2385/2018, 2427/2018, 2466/2018, 2467/2018, 2525/2018, 2838/2019, 2862/2019, 2935/2019, 2951/2019, 3137/2019, 3138/2019, 3223/2019, 3224/2019, 3401/2020, 3492/2020, 3493/2020, 3738/2020, 3948/2020, 3983/2020, 3989/2020, 4019/2021, 4176/2021, 4218/2021, 4683/2021, 4231/2021, 4660/2021, 4658/2021, 4682/2021, 01798/2022, 01878/2022, 01985/2022, 4683/2021, 3948/2020, 02000/2022, 00047/2023, 00320/2023

NCC/TSNi/TA/VOL: 161/2021/124

NCC/TSNi/TA/CERT: 435/2022, 00186/2023

NCC/CERT: 2356/2022, 00561/2023, 00088/2023, 0519/2023, 004558/2024, 00297/2024, 04458/2024, 5876/2025, 00742/2025, 00087/2026

Sultanate of Oman



TRA/TA-R/7145/19_D172338, TRA/TA-R/7240/19_D100428, TRA/TA-R/7244/19_D100428, TRA/TA-R/7383/19_D100428, TRA/TA-R/7384/19_D100428, TRA/TA-R/7481/19_D172338, TRA/TA-R/7524/19_D100428, TRA/TA-R/7604/19_D100428, TRA/TA-R/7704/19_D090024, TRA/TA-R/7752/19_D090024, TRA/TA-R/7867/19_D192564, TRA/TA-R/7871/19_D192564, TRA/TA-R/8052/19_D090024, TRA/TA-R/8056/19_D090024, TRA/TA-R/8084/19_D192564, TRA/TA-R/8150/19_D172338, TRA/TA-R/8158/19_D172338, TRA/TA-R/8171/19_D100428, TRA/TA-R/8240/19_D172338, TRA/TA-R/8480/19_D192564, TRA/TA-R/8649/19_D090024, TRA/TA-R/8749/19_D172338, TRA/TA-R/9347/20_D172338, TRA/TA-R/9664/20_D172338, TRA/TA-R/9675/20_D192564, TRA/TA-R/9676/20_D192564, TRA/TA-R/9682/20_D100428, TRA/TA-R/10209/20_D172249, TRA/TA-R/10345/20_D090024, TRA/TA-R/10363/20_D100428, TRA/TA-R/11110/21_D172338, TRA/TA-R/11179/21_D172249, TRA/TA-R/10614/20_D172249, TRA/TA-R/11980/21_D172338, TRA/TA-R/12440/21_D172338, TRA/TA-R/12742/21_D090258, TRA/TA-R/12743/21_D090258, TRA/TA-R/13040/22_D172338, TRA/TA-R/11110/21_D172338, TRA/TA-R/13697/22_D100428, TRA/TA-R/14975/23_D100428, TRA/TA-R/14722/22_D202897, TRA/TA-R/6945/2014_17/09/2014, TRA/TA-R/15114/23_D172338, TRA/TA-R/13211/22_D172338, TRA/TA-R/15008/23_D172338, TRA/TA-R/13781/23_D100428, TRA/TA-R/15396/23_D090024, TRA/TA-R/12904/21_D213125, TRA/TA-R/12905/21_D213125, TRA/TA-R/16919/23_D202897, TRA/TA-R/16056/23_D100428, TRA/TA-R/15420/23_D172338, TRA/TA-R/16441/23_D172338, TRA/TA-R/16526/23_D172338, TRA/TA-R/16919/23_D202897, TRA/TA-R/17712/24_D172338, TRA/TA-R/18257/23_D100428, TRA/TA-R/20763/2025_1230080, TRA/TA-R/20490/2024_TA125161, TRA/TA-R/19043/24_TA123021, TRA/TA-R/19006/24_TA123023, TRA/TA-R/19209/2024_TA1233347, TRA/TA-R/19227/2024_TA123373, TRA/TA-R/19223/2024_TA123367, TRA/TA-R/19206/2024_TA123344, TRA/TA-R/19547/2024_TA123804, TRA/TA-R/19557/2024_TA123816, TRA/TA-R/19575/2024_TA123835, TRA/TA-R/19005/2024_TA123022, TRA/TA-R/19678/2024_TA123983, TRA/TA-R/19008/2024_TA123025, TRA/TA-R/19970/2024_TA124409, TRA/TA-R/19990/2024_TA124436, TRA/TA-R/20646/2024_TA125372, TRA/TA-R/20490/2024_TA125161, TRA/TA-R/20654/2024_TA125384, TRA/TA-R/20644/2024_TA125370, TRA/TA-R/20492/2024_TA125163, TRA/TA-R/20763/2024_TA125525, TRA/TA-R/21203/2025_TA126089, TRA/TA-R/19674/2024_D172338, TRA/TA-R/20807/2025_TA125593, TRA/TA-R/21203/2025_TA126089, TRA/TA-R/21424/2025_TA126380, TRA/TA-R/22130/2025_TA127290, TRA/TA-R/22183/2025_TA127350, TRA/TA-R/22489/2025_TA127757, TRA/TA-R/22537/2025_TA127816, TRA/TA-R/19674/2024_D172338, TRA/TA-R/23515/2025_TA129159, TRA/TA-R/24009/2025_TA129848, TRA/TA-R/22489/2025_TA127757, TRA/TA-R/24831/2026_TA130988, TRA/TA-R/24285/2025_TA130247, TRA/TA-R/24170/2025_TA130079, TRA/TA-R/24590/2025_TA130638, TRA/TA-R/24656/2025_TA130727 .

Republic of the Philippines



NTC, Type Approved No.:

ESD-1105427C, ESD-1105633C, ESD-1206775C, ESD-1308271C, ESD-1408668C, ESD-1408747C, ESD-1408917C, ESD-1409834C, ESD-1409181C, ESD-1409770C, ESD-1510139C, ESD-1510297C, ESD-1510396C, ESD-1510397C, ESD-1511095C, ESD-1612168C, ESD-1612188C, ESD-1613057C, ESD-1613431C, ESD-1613454C, ESD-1714358C, ESD-1714837C, ESD-1714838C, ESD-1714839C, ESD-1715123C, ESD-1716172C, ESD-1816403C, ESD-1816404C, ESD-1816419C, ESD-1816997C, ESD-1817283C, ESD-1817335C, ESD-1817369C, ESD-1817501C, ESD-1817548C, ESD-1817853C, ESD-1817897C, ESD-1817898C, ESD-1817899C, ESD-1817900C, ESD-1818098C, ESD-1818419C, ESD-1918733C, ESD-1918734C, ESD-1918735C, ESD-1918843C, ESD-1918844C, ESD-1919228C, ESD-1919230C, ESD-1919232C, ESD-1919296C, ESD-1919297C, ESD-1919418C, ESD-1919559C, ESD-1919739C, ESD-1919803C, ESD-1919804C, ESD-1919996C, ESD-1920171C, ESD-1920172C, ESD-1920173C, ESD-1920174C, ESD-1920175C, ESD-1920724C, ESD-1920725C, ESD-1919739C, ESD-1920803C, ESD-2021903C, ESD-2021997C, ESD-2021998C

ESD-CPE-1817719C, ESD-CPE-1920803, ESD-CPE-2003542, ESD-CPE-2003561, ESD-CPE-2103674, ESD-GEC-1402882, ESD-RCE-2022725, ESD-RCE-2023283, ESD-RCE-2024041, ESD-RCE-2024379, ESD-RCE-2125478, ESD-CPE-2103674, ESD-RCE-21257185, ESD-RCE-2127184, ESD-RCE-2127226, ESD-RCE-2128032, ESD-RCE-2228946, ESD-RCE-2024041, ESD-RCE-2229380, ESD-RCE-2230291, ESD-RCE-2332287, ESD-RCE-2333421, ESD-RCE-2334226, ESD-RCE-2334225, ESD-RCE-2231728, ESD-RCE-2231727, ESD-RCE-2334235, ESD-CPE-2043960, ESD-RCE-2231777, ESD-RCE-2231753, ESD-RCE-2436027, ESD-RCE-2437626, ESD-RCE-2436849, ESD-CPE-2403960, ESD-RCE-2541405, ESD-RCE-2542285, ESD-RCE-2543056, ESD-RCE-2543822, ESD-RCE-2127185

Rwanda

RURA/1010402/2019/L123_23.10.2019, RURA/1010402/2019/L128_21.10.2019, RURA/1010402/2020/L1069, RURA/1010402/2020/L1705_20.05.2020, RURA/101042/2020/L6997_24.09.2020,

RURA/ICT/AUT/200140090_17.11.2020, RURA/ICT/AUT/200140122_17.11.2020, RURA/ICT/AUT/210165696_10.06.2021, RURA/ICT/AUT/210172215_21.07.2021, RURA/ICT/AUT/210172964_30.07.2021, RURA/ICT/AUT/210178685_30.08.2021, RURA/ICT/AUT/210190642_22.10.2021, RURA/ICT/AUT/210148185_31.01.2021, RURA/ICT/AUT/210149593_18.02.2021, RURA/ICT/AUT/210172964_30.06.2021, RURA/ICT/AUT/210173357_03.08.2021, RURA/ICT/AUT/210194843_11.11.2021, RURA/ICT/AUT/210194847_11.11.2021, RURA/ICT/AUT/220213502_11.02.2022, RURA/ICT/AUT/220221142_09.03.2022, RURA/ICT/AUT/220221144_09.03.2021, RURA/ICT/AUT/220232513_11.05.2022, RURA/ICT/AUT/220264765_05.10.2022, RURA/ICT/AUT/220270155_28.10.2022,

RURA/ICT/AUT/220272401_14.11.2022, RURA/ICT/AUT/220273457_15.11.2022, RURA/ICT/AUT/220275518_22.11.2022, RURA/ICT/AUT/220280879_19.12.2022, RURA/ICT/AUT/230211868_10.05.2023, RURA/ICT/AUT/220271948_09.11.2022, RURA/ICT/AUT/220271951_09.11.2022, RURA/ICT/AUT/230311868_10.05.2023, RURA/ICT/AUT/230343093_27.09.2023, RURA/ICT/AUT/2403771708_28.02.2024, RURA/ICT/AUT/230353517_05.11.2023, RURA/ICT/AUT/2303275167_25.06.2023, RURA/ICT/AUT/230320586_20.06.2023, RURA/ICT/AUT/240425975_20.08.2024, RURA/ICT/AUT/240377170_28.02.2024, RURA/ICT/AUT/240455424_25.10.2024, RURA/ICT/AUT/250503380_21.04.2025.

026HD/ICT/RURA/018_11.01.2018, 093HD/ICT/RURA/018_19.02.2018, 181HD/ICT/RURA/019_07.03.2019, 192HD/ICT/RURA/018_13.04.2018, 265HD/ICT/RURA/018_22.05.2018, 266HD/ICT/RURA/018_22.05.2018, 277HD/ICT/RURA/019_11.04.2019, 278HD/ICT/RURA017_25.07.2017, 279HD/ICT/RURA/019_11.04.2019, 313HD/ICT/RURA/018_08.06.2018, 334HD/ICT/RURA/018_13.06.2018, 335HD/ICT/RURA/018_14.06.2018, 343HD/ICT/RURA/018_22.08.2017, 348HD/ICT/RURA/019_10.05.2019, 349HD/ICT/RURA/018_22.06.2018, 355HD/ICT/RURA/018_22.06.2018, 356HD/ICT/RURA/018_22.06.2018, 357HD/ICT/RURA/018_22.06.2018, 368HD/ICT/RURA/018_29.06.2018, 399HD/ICT/RURA/019_03.06.2019, 401HD/ICT/RURA/018_09.07.2018, 433HD/ICT/RURA/019_19.06.2019, 444HD/ICT/RURA/019_19.06.2019, 448HD/ICT/RURA/018_27.07.2018, 449HD/ICT/RURA/018_27.07.2018, 537HD/ICT/RURA/018_14.09.2018, 607HD/ICT/RURA/018_11.10.2018, 645GM/ICT/RURA/019_11.09.2019, 646GM/ICT/RURA/019_11.09.2019, 712HD/ICT/RURA/018_04.12.2018, 742HD/ICT/RURA/018_14.12.2018, 1350HD/CMR/RURA/015_08.12.2015, RURA/ICT/AUT/220251514_08.10.2022, RURA/ICT/AUT/250549204_24.06.2025, RURA/ICT/AUT/250568931_26.08.2025, RURA/ICT/AUT/260638748_28.01.2026 .

Republic of Senegal

AGREE PAR ARPT SENEGAL

Numéro d'agrément : XXXXXX/AG/ER

071845/AG/ER,071821/AG/ER,071755/AG/ER,071710/AG/ER,071617/AG/ER,071414/AG/ER,071395/AG/ER,071394/AG/ER,071347/AG/ER,071346/AG/ER,071186/AG/ER,071185/AG/ER,071149/AG/ER,071148/AG/ER,071099/AG/ER,0710996/AG/ER,070984/AG/ER,070847/AG/ER,070848/AG/ER,070680/AG/ER,070650/AG/ER,070572/AG/ER,070571/AG/ER,070214/AG/ER,071892/AG/ER,071920/AG/ER,072048/AG/ER,072231/AG/ER, 072100/AG/ER, 072164/AG/ER, 072164/AG/ER, 072183/AG/ER, 072231/AG/ER, 072453/AG/ER, 072469/AG/ER, 072536/AG/ER, 072588/AG/ER, 072485/AG/ER, 072474/AG/ER, 072264/AG/ER, 072613/AG/ER, 072588/AG/ER, 072646/AG/ER, 072722/AG/ER, 072739/AG/ER, 072814/AG/ER, 072877/AG/ER, 073140/AG/ER, 072131/AG/ER, 072132/AG/ER

Republic of Serbia



W005 17, W005 18, W005 19, W005 20, W005 21, W005 22, W005 23, W005 24, W005 25, W005 26

W011 14, W011 15, W011 16, W011 17, W011 18, W011 19, W011 20, W011 21, W011 22, W011 23, W011 24, W011 25, W011 26

W038 19, W038 20, W038 21, W038 22, W038 23c, W0038 24, W0038 25, W0038 26

Republic of Singapore

Complies with
IMDA Standards
BD104682

Abb. 2

Complies with IMDA Standards: DA103238, DA103787, DA103858, DA104328, DA104682, DA104812, DA105282, DA107248, DA107974, DB03227, DB101762, DB103858, DB106879, DB107220, DB106879.

Registration Number: G1594-19, G1858-19, N0039-21, N0254-17, N0254-17, N0356-20, N0688-15, N0721-15, N0982-20, N1085-21, N1453-20, N1599-19, N1629-17, N1630-17, N2052-18, N2053-18, N2069-19, N2152-20, N2285-19, N2404-19, N2405-19, N2415-18, N2420-18, N2565-18, N2673-18, N2700-18, N2706-19, N2860-18, N2991-18, N2992-18, N3005-18, N3083-18, N3277-20, N3278-20, N3548-18, N3577-18, N3888-16, N3970-18, N4123-19, N4334-20, N4347-21, S5104-21, N5264-21, N5963-21, N0708-17, N1019-22, N1568-22, N1851-22, N1898-22, N3020-22, N3453-22, N3456-22, N3450-22, N3835-22, G0443-21, N3888-16, N0254-17, N0708-17, N5372-22, N5373-22, N6052-22, N0374-23, N0415-23, N0414-23, N1159-23, N5856-20, N1233-23, N1291-23, N1631-23, N2673-23, N3098-23, N3096-23, N3688-18, N3555-18, G1231-23, N0452-23, S3262-23, S3263-23, N3567-23, N3097-23, N0951-24, N2161-24, N1153-24, N1074-24, N1186-24, N1600-19, N2308-24, N2309-24, N2875-24, N3160-24, DA104682, N4887-19, N5684-24, N5760-24, N5297-19, N5296-19, N0356-20, N0477-20, ESER/25/0054, ESER/25/1995, ESER/25/2062, ESER/25/2132, ESER/25/2405, ESER/25/2469, N3428-20, GER/25/0042, N2652-20, N2654-20, N2653-20, N2837-20, ESER/25/3416, N3429-20, N3433-20, N3430-20, ESER/25/4582, N4381-21, N4380-21, N0337-23, N0338-23, ESER/26/0973, ESER/25/4619, ESER/25/5095, ESER/25/5248, N5835-20, ESER/25/6468, ESER/25/7466, ESER/25/7504, ESER/26/0223, ESER/26/0363, ESER/26/0627, ESER/26/0973.

Republic of South Africa



ICASA APPROVED:

TA-2009/464, TA-2010/218, TA-2010/1235, TA-2011/615, TA-2012/321, TA-2012/1747, TA-2012/1821, TA-2013/1679, TA-2013/1681, TA-2013/1682, TA-2013/1680, TA-2013/1683, TA-2013/2085, TA-2013/2465, TA-2013/2503, TA-2014/176,

TA-2014/212, TA/2014/792, TA/2014/982, TA-2014/1719, TA-2014/1783, TA-2014/1784, TA-2014/1887, TA-2014/2108, TA-2014/2597, TA-2015/517, TA-2015/2011, TA-2015/2084, TA-2016/169, TA-2016/501, TA-2016/820, TA-2016/863, TA-2016/1449, TA-2016/2568, TA-2016/2601, TA-2016/2759, TA-2016/3407, TA-2016/3539, TA-2016/3541, TA-2017/052, TA-2017/127, TA-2017/209, TA-2017/2013, TA-2017/2824, TA-2017/3480, TA-2017/2824, TA-2018/175, TA-2018/280, TA-2018/732, TA-2018/842, TA-2018/843, TA-2018/844, TA-2018/845, TA-2018/996, TA-2018/997, TA-2018/998, TA-2018/999, TA-2018/1091, TA-2018/1095, TA-2018/1205, TA-2018/1408, TA-2018/1649, TA-2018/1650, TA-2018/1806, TA-2018/1814, TA-2018/1815, TA-2019/1853, TA-2018/2177, TA-2018/2251, TA-2018/2776, TA-2018/2777, TA-2018/2868, TA-2018/3141, TA-2018/3466, TA-2018/3561, TA-2018/3974, TA-2018/5159, TA-2019/115, TA-2019/348, TA/2019/550, TA-2019/582, TA-2019/583, TA-2019/1110, TA-2019/1111, TA-2019/1410, TA-2019/1853, TA-2019/2347, TA-2019/2348, TA-2019/5101, TA-2019/5116, TA-2019/5167, TA-2020/4885, TA-2020/5217, TA-2020/5480, TA-2020/6261, TA-2020/6392, TA-2020/6394, TA-2020/7066, TA-2020/7103, TA-2020/7390, TA-2021/0295, TA-2021/0637, TA-2021/7762, TA-2021/0949, TA-2021/1613, TA-2021/1608, TA-2021/2146, TA-2021/2307, TA-2021/2501, TA-2021/3273, TA-2022/3766, TA-2021/0637, TA-2022/0625, TA-2022/0298, TA-2022/0298, TA-2022/03215, TA-2020/7103, TA-2022/0124, TA-2020/5443, TA-2022/1222, TA-2022/3229, TA-2023/3353, TA-2023/0199, TA-2023/0338, TA-2023/0349, TA-2022/3381, RSS/NCA/TA/3/166, TA-2023/0349, TA-2023/0338, TA2023/0892, TA-2023/1203, TA-2023/2091, TA-2023/1813, TA-2005/614, TA-2024/0552, TA-2024/0552, TA-2019/348, TA-2023/0232; TA-2023/2829, TA-2023/3425, TA-2024/3199, TA-2024/0519, TA-2024/0867, TA-2024/2726, TA-2025/0169, TA-2025/1068, TA-2025/1044, TA-2025/2039, TA-2025/2524, TA-2025/2862, TA-2025/3308, TA-2025/4875.

Prathet Thai

เครื่องวิทยุคมนาคมนี้ ได้รับยกเว้น ไม่ต้องได้รับใบอนุญาตให้มี ใช้ซึ่งเครื่องวิทยุคมนาคมหรือตั้งสถานีวิทยุคมนาคมตามประกาศ กสทช. เรื่อง เครื่องวิทยุคมนาคม และสถานีวิทยุคมนาคมที่ได้รับยกเว้นไม่ต้องได้รับใบอนุญาตวิทยุคมนาคมตามพระราชบัญญัติวิทยุคมนาคม พ.ศ. 2498

nano. | โทรคมนาคม
กำกับดูแลเพื่อประชาชน
Call Center 1200 (InswS)

W21-0762

Abb. 3



Abb. 4

- 1) เครื่องโทรคมนาคมและอุปกรณ์นี้ มีความสอดคล้องตามมาตรฐานหรือข้อกำหนดของ กทช.
- 2) เครื่องวิทยุคมนาคมนี้ มีระดับการแผ่คลื่นแม่เหล็กไฟฟ้า สอดคล้องตามมาตรฐานความปลอดภัยต่อสุขภาพของมนุษย์จากการใช้เครื่องวิทยุคมนาคมที่คณะกรรมการกิจการโทรคมนาคมแห่งชาติประกาศกำหนด

NBCTC ID: A57003-17, A57004-14, A57004-17, A57005-14, A57006-15, A57006-19, A57006-18, A57008-14, A57009-14, A57012-16, B38083-20, B57008-21, B57007-21, A57014-21, B57003-22, S01561-22, S01559-22, S03635-22, S00224-23, S4117-22, A57014-21, SD01415-23, A75007-22, S03477-22, SD02328-23, SD01325-23, SD03081-23, SD02729-23, A57003-22, A75003-22, S01559-22, S01729-22, A75004-22, A75004-22, SD01290-25, C64001-25, A75024-25, SD04219-25, SD03730-25, SD04909-25

Türkiye Cumhuriyeti

Telsiz ekipmanı ve uygunluk beyanları hakkında daha fazla bilgi için, bkz: www.volkswagen.com/general-info.

Countries outside the U.S. that approve and use radio equipment under U.S. FCC policy:



FCC ID: 2AAJCBR20, FCC ID: 2AAJCBR21, FCC ID: 2AAJCBR22, FCC ID: 2AA98, FCC ID: 2AA98-COLOUR5C, FCC ID: 2AA98-MEDIUM5C, FCC ID: 2AA98-MEDIUM5C21, FCC ID: 2AA98A, FCC ID: 2AHPN-WLC, FCC ID: 2AOUZ17101001, FCC ID: 2AOUZ17101002, FCC ID: 2AOUZ17101010, FCC ID: 2AOUZ17101022, FCC ID: 2AOUZ17101023, FCC ID: 2AOUZ17101031, FCC ID: 2AOUZ17101032, FCC ID: 2AOUZ17101033, FCC ID: 2AOUZ17101034, FCC ID: 2AOUZ17101041, FCC ID: 2AOUZ17101042, FCC ID: 2AOUZ17101043, FCC ID: 2AOUZ17101051, FCC ID: 2AOUZ17101052, FCC ID: 2AOUZ17101053, FCC ID: 2AOUZ17101054, FCC ID: 2AOUZ17101055, FCC ID: 2AOUZ17101056, FCC ID: 2AOUZ17101057, FCC ID: 2AOUZ17101071, FCC ID: 2AOUZ17101072, FCC ID: 2AOUZ18020531, FCC ID: 2AOUZ18020532, FCC ID: 2AOUZ18020533, FCC ID: 2AOUZ18020534, FCC ID: 2AOUZ18100931, FCC ID: 2APOM-

MQBA0, FCC ID: 2AVXWWSBRC001, FCC ID: 2AXPS-WPC003-1, FCC ID: 772C-LB1FD, FCC ID: BEJLCW05-VV05, FCC ID: BEJ-MIB2, FCC ID: BEJMIB2PQ, FCC ID: BEJ-MEBICAS3, FCC ID: BEJ-MIBPQMIN, FCC ID: BEJ-MIB301, FCC ID: BEJTLAHW3IU-E, FCC ID: BEJTLAHW3IU-N, FCC ID: BEJTLVHE4IU-E, FCC ID: BEJTLVHE4IU-N, FCC ID: BEJTLVHM3IU-E, FCC ID: BEJTLVHM3IU-N, FCC ID: BEJTLVM3IU-N, FCC ID: BEJTUVMO1IU, FCC ID: CWTUGZZF1, FCC ID: CWTUGZZF2, FCC ID: IYZVK2, FCC ID: KR5-BCMEVOC, FCC ID: KR5FS14T, FCC ID: KR5FS14TK, FCC ID: KR55NA920791A, FCC ID: LTQR3TR, FCC ID: NBG010180T, FCC ID: NBG010905A, FCC ID: NBG011719A, FCC ID: NBG013854, FCC ID: NBG01RS4, FCC ID: NBG011719A, FCC ID: NBG10176, FCC ID: NBG9068, FCC ID: NBG92596263, FCC ID: NBGBCMEVO, FCC ID: NBGBCMEV05, FCC ID: NBGBCM2R, FCC ID: KR5BCM37WB, FCC ID: NBGFS09P03, FCC ID: NBGFS12A, FCC ID: NBGFS12A01, FCC ID: NBGFS12P, FCC ID: NBGFS12P01, FCC ID: NBGFS12PM, FCC ID: NBGFS12P01M, FCC ID: NBGFS125C, FCC ID: NBGFS125C1, FCC ID: NBGFS125C5, FCC ID: NBGFS173NP, FCC ID: NBGFS173NPM, FCC ID: NBGFS173NR, FCC ID: NBGFS1744M, FCC ID: NBGFS19, FCC ID: NBGFS191, FCC ID: NBGFS93N, FCC ID: NBGMQBBB, FCC ID: NBGMQBBH, FCC ID: NBGPQ12P01, FCC ID: NBGRSB19, FCC ID: NF3-FR5CPEC, FCC ID: NF3-LRR3SCU, FCC ID: NF3-LRR4, FCC ID: NF3-MRR1PLUS, FCC ID: NF3-MRR1REAR, FCC ID: NF3-MRREVO14F, FCC ID: NF3-LRR3SCU, FCC ID: NT8-FPK8MMO5D, FCC ID: NT8-VVMIBREGIO, FCC ID: NZLADHLS, FCC ID: NZLJCI-BUSHL4, FCC ID: OAYARS4B, FCC ID: OAYARS5B, FCC ID: OYGTSS-RE4UD, FCC ID: OYGTSSRE4UF, FCC ID: OYGTSSSG4G5, FCC ID: QIPALAS6A-US, FCC ID: QISME919BS-567BN, FCC ID: QISME919BS-567BNB, FCC ID: QZ9-KA3, FCC ID: RK7MBC-NAR, FCC ID: RK7MBC-NAR2, FCC ID: RK7185-00, FCC ID: RK7186-00, FCC ID: RX2BNFHL, FCC ID: RX2BNFLL, FCC ID: T8GA270, FCC ID: T8GA475, FCC ID: T8GA476, FCC ID: T8GP114, FCC ID: VPYLB1KD, FCC ID: WJLHT-5, FCC ID: NF3-FR5CUEC, FCC ID: NBG01RS55, FCC ID: NF3-F5CP42, FCC ID: NBG01RS53, FCC ID: NBGFS125C1, FCC ID: BEJ-MIB30IVR-E, FCC ID: BEJTLVHM3IU-N, FCC ID: 2AXPS-WPC003-1, FCC ID: 2AXPS-WPC003-5, FCC ID: 2ACC7DDAECE02, FCC ID: BEJTLVUM3IU-W, FCC ID: BEJTLVUM3IU-W, FCC ID: BEJTLVUM3IU-E, FCC ID: BEJTLVUM3IU-N, FCC ID: BEJTLVUM3IU-N, FCC ID: NT8-FPK815DTR2, FCC ID: NBGFS19015, FCC ID: NBGFS195, FCC ID: BEJ-ICAS3GP, FCC ID: NBGFS1915, FCC ID: BEJTLVLM3IU-N, FCC ID: BEJTLVUM3IU-W, FCC ID: BEJTLVUM3IU-N, FCC ID: BEJTLVUM3IU-E, FCC ID: BEJTLVUE4IU-E, FCC ID: BEJTLVUE4IU-N, FCC ID: BEJTLVUE4IU-W, FCC ID: QZ9-DCB, FCC ID: 2BAHD-EC30693, FCC ID: YGONFCTGSAU336, FCC ID: KR5I22U, FCC ID: BEJ-MIB30IVR-E01, FCC ID: BEJ-MIB30I, FCC ID: BEJ-MIB3GP, FCC ID: YGONFCTGSAU336, FCC ID: YG0BUEGELNFC, FCC ID: YG0FLUSHNFC, FCC ID: 2A6TC-HFA30, FCC ID: T8GCONMODMQB, FCC ID: KR5I2B, FCC ID: KR5I25U, FCC ID: 2A6WXXWCSKD11A, FCC ID: T8GCONMODMEB, FCC ID: OYGTSSSH4, FCC ID: 2A6TC-NFCGATEWAY .

Interference Statement

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and

(2) This device must accept any interference received, including interference that may cause undesired operation.

CAUTION TO USERS: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

FCC RF Exposure Statement

FCC ID: RK7MBC-NAR

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. End users must follow the specific operating instruction for satisfying RF exposure compliance. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

This is a CONSUMER device.

BEFORE USE, you MUST REGISTER THIS DEVICE with your wireless provider and have provider's consent. Most wireless providers consent to the use of signal boosters. Some providers may not consent to the use of this device on their network. If you are unsure, contact your provider.

You MUST operate this device with approved antennas and cables as specified by the manufacturer. Antennas MUST be installed at least 20 cm (8 inches) from any person.

You MUST cease operating this device immediately if requested by FCC or a licensed wireless service provider.

WARNING: E911 location information may not be provided or may be inaccurate for calls served by using this device.

Wireless Notice

This device complies with FCC radiation exposure limits set forth for an uncontrolled environment and meets the FCC radio frequency (RF) Exposure Guidelines. This transmitter must not be colocated or operating in conjunction with any other antenna or transmitter.

FCC Class A digital device notice

NOTE: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance

with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

FCC Class B digital device notice

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Ukraine / Україна

Для отримання додаткової інформації про радіобладнання та декларації про відповідність див www.volkswagen.com/generalinfo.



BSD 3.0	24,05 - 24,25 GHz	20 dBm
LCA 2.0	24,05 - 24,25 GHz	20 dBm
RS4	24,05 - 24,25 GHz	20 dBm
RSS.3	76,0 - 77,0 GHz	27,2 dBm
RSS.5	76,0 - 77,0 GHz	32,8 dBm

повний текст декларації про відповідність доступний на веб-сайті за такою адресою: www.volkswagen.com/generalinfo.

1APT V R3TR, 1BOSCO001, 1HELARS40, 109, 10094.002801-15, 10094.004984-17, 10094.004985-17, 10094.004986-17, 10094.006565-18, 10094.007280-19, 0848, 486.25-CET, 920697B, TLAHW3IU-E, TLAHW3IU-W, TLVHM3IU-E, TLVLM3IU-E, TLVHM3IU-W, 1CONT0001

1.001.010758/M1-16, 1.001.017067-18-TE, 1.001.018566-19-TE, 1.001.018601-19-TE, 1.001.018646-19-TE, 1.001.018774-19-TE, 1.001.018968-19-TE, 1.001.019275-19-TE, 1.001.019287-19-TE, 1.001.020220-19-TE, 1.001.020355-19-TE, 1.001.020702-19-TE, 1.001.020853-19-TE, 1.001.020929-19-TE, 1.001.021241-20-TE, 1.001.021295-20-TE, 1.001.022108-20-TE

UA.R.TR.052.041-21, UA.R.TR.052.081-20, UA.R.TR.052.088-19, UA.R.TR.052.089-19, UA.R.TR.052.130-20, UA.R.TR.052.161-19, UA.R.TR.052.187-19, UA.R.TR.052.189-19, UA.R.TR.052.190-19, UA.R.TR.052.194-19, UA.R.TR.052.215-21, UA.R.TR.052.433-19, UA.R.TR.052.529-19, UA.R.TR.052.533-19, UA.R.TR.052.598-19, UA.R.TR.052.613-19, UA.R.TR.052.658-19, UA.R.TR.052.634-19, UA.R.TR.052.068-22, UA.R.TR.052.169-23, UA.R.TR.052.073-24, UA.R.TR.052.051-25.

UA.TR.028: 680.13-CET, 680.14-CET, 680.15-CET, 2423.10-CET, 2423.17-CET, 2423.21-CET, 2423.31-CET, 2423.32-CET, 2423.33-CET, 2423.44-CET, 2423.49-CET, 2423.50-CET, 2423.51-CET, 2539.8-CET, 2539.9-CET, 2539.10-CET, 2539.12-CET, 2539.13-CET, 2539.15-CET, 2539.17-CET, 2539.19-CET, 2539.20-CET, 2539.21-CET, 2539.22-CET, 2539.23-CET, 2539.30-CET, 2539.31-CET, 2539.45-CET, 2579.1-CET, 2579.2-CET, 2580.4-CET, 2580.5-CET, 2610.2-CET, 2423.62.2-CET

UA.TR.030.026039-19, UA.TR.030.028039-19, UA.TR.109.R.0009-18, UA.TR.109.R.0016-19, UA.TR.109.R.0021-19, UA.TR.109.R.0023-19, UA.TR.109.R.0026-19, UA.TR.109.R.0028-19, UA.TR.109.R.0029-19, UA.TR.109.R.0030-19, UA.TR.109.R.0032-19, UA.TR.109.R.0042-20, UA.TR.109.R.0057-21, UA.TR.109.R.0082-20, UA.TR.109.R.0133-19, UA.TR.109.R.0155-18, UA.TR.109.R.0162-19, UA.TR.109.R.0168-19, UA.TR.109.R.0174-18, UA.TR.109.R.0179-18, UA.TR.109.R.0187-18, UA.TR.109.R.0201-19, UA.TR.109.R.0212-19, UA.TR.109.R.0214-18, UA.TR.109.R.0249-18, UA.TR.109.R.0259-18, UA.TR.109.R.0281-18, UA.TR.109.R.0282-18, UA.TR.109.R.0302-18, UA.TR.109.R.0304-18, UA.TR.109.R.0305-18, UA.TR.109.R.0307-18, UA.TR.109.R.0313-18, UA.TR.109.R.0333-20, UA.TR.109.R.0336-19, UA.TR.109.R.0337-19, UA.TR.109.R.0344-18, UA.TR.109.R.0345-18, UA.TR.109.R.0374-18, UA.TR.109.R.0375-18, UA.TR.109.R.0376-18, UA.TR.109.R.0389-18, UA.TR.109.R.0394-18, UA.TR.109.R.0411-18, UA.TR.109.R.0425-18, UA.TR.109.R.0426-18, UA.TR.109.R.0438-18, UA.TR.109.R.0467-18, UA.TR.109.R.0598-18, UA.TR.109.R.0645-18, UA.TR.109.R.0340-21, UA.TR.109.R.0028-22, UA.TR.109.R.0174-18, UA.TR.109.R.0389-18, UA.TR.109.R.0241-22, UA.TR.109.R.0252-22, UA.TR.109.R.0250-22, UA.TR.109.R.0069-23, UA.TR.109.R.0070-23, UA.TR.109.R.0037-23, UA.TR.109.R.0068-23, UA.TR.109.R.0105-23, UA.TR.109.R.252-22, UA.TR.109.R.0049-23, UA.TR.109.R.0141-23, UA.TR.001.0355.30.00616-22, UA.TR.109.R.0517-25, UA.TR.109.R.0572-25

UA RF: 1BOSCO001, UA RF: 1CONTO001, UA RF: 1CONTO002, UA RF: 1HELABSD3, UA RF: 1HELARS40, UA RF: 1BOSCO016, UA RF: 1BOSCO017, UA RF: 1BOSCO018, UA RF: 1HELARS53, UA RF: 1HELARS55, UA.TR.109.R.0274-21, UA.TR.109.R.0273-21

UA.032.CT.0026-19, UA.032.CT.0030-18, UA.032.CT.0083-19, UA.032.CT.0084-19, UA.032.CT.0107-19, UA.032.CT.0188-18, UA.032.CT.0221-20, UA.032.CT.0224-19, UA.032.CT.0225-19, UA.032.CT.0225-21, UA.032.CT.0226-19, UA.032.CT.0227-19, UA.032.CT.0313-19, UA.032.CT.0527-19, UA.032.CT.0187-22, UA.032.CT.280-22, UA.32.CT.RED.0013-25, UA.32.CT.0187-22

04-1214/123.

UKR.355-10/233, UKR.355-11/233, UA.R.TR.052.089-19, UA.R.TR.052.091-23, UA.R.TR.052.044-23, UA.R.TR.052.090-23, UA.R.TR.052.204-22, UA.TR.109.R.0253-22

Socialist Republic of Vietnam

ICT



SunTech VietNam Technology Company Limited, C00082015, SUNTECH VietNam, SUNTECH VN:

71/CVT-TT3, 220/CVT-TT3

220221.01-TN, 220208.14-TN, 773/TTDCLL-CN, 210816.05-TN, 210526.20-TN, 210816.04-TN, 3568/CVT-CNDV, 210526.21-TN, 2357/CVT-CL, 220310.03-TN, 220321.12-TN, 220607.09-TN, 230526.13-TN, 230526.12-TN

, A0858170820AF04A3, A209161221AA04A3, A1099061022AE01A3, A1100061022AE01A3, A0590260523AF04A3, B0401220321AE01A3, B0411230321AF04A3, B1189140520AF04A2, B2110171214BE11A2, B0423060422AF04A3, B0609240522AF04A3, B0620300522AE01A3, 0735240622AF04A3, B0734240622AF04A3, B0812080722AF04A3, B0813080722AF04A3, B0814080722AF04A3, B0808080722AF04A3, B0809080722AF04A3, B0810080722AF04A3, B0811080722AF04A3, B0815080722AF04A3, B0816080722AF04A3, B1093160822AE01A3, B1092160822AE01A3, B1089160822AE01A3, B1437261022AF04A3, B1647291122AF04A3, B1646291122AF04A3.

C0032060315BE01A2, C0032210220AF04A2, C0033060315BE01A2, C0055100417AF04A2, C0101230419AF04A2, C0118220519AF04A2, C0119220519AF04A2, C0124040520AF04A2, C0135110520AF04A2, C0141020718AF04A2, C0158100620AF04A2, C0159100620AF04A2, C0161110620AF04A2, C0162110620AF04A2, C0163110620AF04A2, C0174020818AF04A2, C0175020818AF04A2, C0181260620AF04A2, C0182260620AF04A2, C0183260620AF04A2, C0184260620AF04A2, C0197111217AF04A2, C0229240919AF04A2, C0238150321AF04A3, C0239150321AF04A3, C0289310321AF04A3, C0307010920AF04A3, C0308010920AF04A3, C0309010920AF04A2, C0319091219AF04A2, C0470201120AF04A3, C0438061120AF04A3, C0136090022AF04A3, C019728022AF04A3, C0237070322AF04A3, C0577170522AF04A3, C1064310822AF04A3, C0409171023AF04A3, C003030124AF04A33, B0471130324AF04A3, C0500180324AF04A3, B0770070524AE01A3, C0430230724AF04A3, B0770070524AE01A3, C0431230724AF04A3, C0671011024AE01A3, A1125041224AF61A4, A1126041224AF61A4, C0967241224AF71A3, C0968241224AF71A3, C0008030125AF71A3, C0030070125AF71A4, C0059160125AF71A4, C0060160125AF71A4

Hella KGaA Hueck Co.: A0858170820AF04A3, B134510122AF04A3, B1346101022AF04A3, B1347101022AF04A3, B1348101022AF04A3, B1349101022AF04A3, C0013190118AF04A2, C0036120121AF04A3, C0065120418AF04A2, C0068190418AF04A2, C0080180319AF04A2, C0092300320AF04A2, C0100100420AF04A2, C0163150719AF04A2, C0177011117AF04A2, C0178011117AF04A2, C0181230221AF04A3, C0205060916AF04A2, C0226170918AF04A2, C0314061219AF04A2, C0952190821AF04A3, C0953190821AF04A3,

C1071270921AF04A3, C1099011021AF04A3, C1100011021AF04A3,
C0136090222AF04A3, C0197280222AF04A3, C1239021122AF04A3,
C124002122AF04A3, C1798281222AF04A2, B0643170523AF04A3,
B0458140423AF04A3, B1566051121AE01A3, 231009.05-TN,
230911.13-TN, B0456110324AF03A3, B0454110324AF03A3,
C0147180324AF04A3, C0386280624AF04A3, C0219070325AF1A3,
TVN-250329004.T01, C0417130525AF61A3, C0655090725AF61A3,
C0862200825AF91A3, C0861200825AF91A3, C0976190925AF41A3,
C0975190925AF41A3, C0977190925AF41A3, C0974190925AF41A3,
C1001240925AF61A3, C1006240925AF71A3, C1005240925AF71A3,
C1004240925AF71A3, C1000240925AF61A3, C1003240925AF61A3,
C10002240925AF61A3, C1000240925AF61A3, C1050061025AF61A3,
C1119211025AF71A3.
ICT Motor: A1900761



USA

Certificates

More entries at :

www.volkswagen.com/generalinfo

FCC ID: 2AAJCBR20, FCC ID: 2AAJCBR21, FCC ID: 2AAJCBR22, FCC ID: 2AA98, FCC ID: 2AA98-COLOUR5C, FCC ID: 2AA98-MEDIUM5C, FCC ID: 2AA98-MEDIUM5C21, FCC ID: 2AA98A, FCC ID: 2AHPN-WLC, FCC ID: 2AOUZ17101001, FCC ID: 2AO-UZ17101002, FCC ID: 2AOUZ17101010, FCC ID: 2AOUZ17101022, FCC ID: 2AOUZ17101023, FCC ID: 2AOUZ17101031, FCC ID: 2AO-UZ17101032, FCC ID: 2AOUZ17101033, FCC ID: 2AOUZ17101034, FCC ID: 2AOUZ17101041, FCC ID: 2AOUZ17101042, FCC ID: 2AO-UZ17101043, FCC ID: 2AOUZ17101051, FCC ID: 2AOUZ17101052, FCC ID: 2AOUZ17101053, FCC ID: 2AOUZ17101054, FCC ID: 2AO-UZ17101055, FCC ID: 2AOUZ17101056, FCC ID: 2AOUZ17101057, FCC ID: 2AOUZ17101071, FCC ID: 2AOUZ17101072, FCC ID: 2AO-UZ18020531, FCC ID: 2AOUZ18020532, FCC ID: 2AOUZ18020533, FCC ID: 2AOUZ18020534, FCC ID: 2AOUZ18100931, FCC ID: 2APOM-MQBAO, FCC ID: 2AVXWWSBRC001, FCC ID: 2AXPS-WPC003-1, FCC ID: 772C-LB1FD, FCC ID: BEJLVCW05-VVW5, FCC ID: BEJ-MIB2, FCC ID: BEJMIB2PQ, FCC ID: BEJ-MEBICAS3, FCC ID: BEJ-MIBPQMIN, FCC ID: BEJ-MIB301, FCC ID: BEJTLAHW3IU-E, FCC ID: BEJTLAHW3IU-N, FCC ID: BEJTLVHE4IU-E, FCC ID: BEJTLV-HE4IU-N, FCC ID: BEJTLVHM3IU-E, FCC ID: BEJTLVHM3IU-N, FCC ID: BEJTLVHM3IU-N, FCC ID: BEJ-TUVM01IU, FCC ID: CWTUGZZF1, FCC ID: CWTUGZZF2, FCC ID: IYZVK2, FCC ID: KR5-BCMEVOC, FCC ID: KR5FS14T, FCC ID: KR5FS14TK, FCC ID: KR55NA920791A, FCC ID: LTQR3TR, FCC ID: NBG010180T, FCC ID: NBG010905A, FCC ID: NBG011719A, FCC ID: NBG013854, FCC ID: NBG01RS4, FCC ID: NBG011719A, FCC ID: NBG10176, FCC ID: NBG9068, FCC ID: NBG92596263, FCC ID: NBGBCMEVO, FCC ID: NBGBCMEVO5, FCC ID: NBGBCM2R, FCC ID: KR5BCM37WBL, FCC ID: NBGFS09P03, FCC ID: NBGFS12A, FCC ID: NBGFS12A01, FCC ID: NBGFS12P, FCC ID: NBGFS12P01, FCC ID: NBGFS12PM, FCC ID: NBGFS12P01M, FCC ID: NBGFS125C, FCC ID: NBGFS125C1, FCC ID: NBGFS125CS, FCC ID: NBGFS173NP, FCC ID: NBGFS173NPM, FCC ID: NBGFS173NR, FCC ID: NBGFS1744M, FCC ID: NBGFS19, FCC ID: NBGFS191, FCC ID: NBGFS93N, FCC ID: NBGMQB8B, FCC ID: NBGMQB8B, FCC ID: NBGPQ12P01, FCC ID: NBGRSB19, FCC ID: NF3-FR5CPEC, FCC ID: NF3-LRR3SCU, FCC ID: NF3-LRR4, FCC ID: NF3-MRR1PLUS, FCC ID: NF3-MRR1REAR, FCC ID: NF3-MRREVO14F, FCC ID: NF3-LRR3SCU, FCC ID: NT8-FPKBIMM05D, FCC ID: NT8-VVMIBREGIO, FCC ID: NZLADHL5D, FCC ID: NZLJCI-BUSHL4, FCC ID: OAYARS4B, FCC ID: OAYARS5B, FCC ID: OYGTSS-RE4UD, FCC ID: OYGTSSRE4UF, FCC ID: OYGTSSSG4G5, FCC ID: QIPA-LAS6A-US, FCC ID: QISME919BS-567BN, FCC ID: QISME919BS-567BND, FCC ID: QZ9-KA3, FCC ID: RK7MBC-NAR, FCC ID: RK7MBC-NAR2, FCC ID: RK7185-00, FCC ID: RK7186-00, FCC ID: RX2BNFHL, FCC ID: RX2BNFLL, FCC ID: T8GA270, FCC ID: T8GA475, FCC ID: T8GA476, FCC ID: T8GP114, FCC ID: VPYLB1KD, FCC ID: WJLHT-5, FCC ID: NF3-FR5CUEC, FCC ID: NBG01RS55,

FCC ID: NF3-F5CP42, FCC ID: NBG01RS53, FCC ID: NBGFS125C1, FCC ID: BEJ-MIB30IVR-E, FCC ID: BEJTLVHM3IU-N, FCC ID: 2AXPS-WPC003-1, FCC ID: 2AXPS-WPC003-5, FCC ID: 2ACC7DDAECE02, FCC ID: BEJTLVUM3IU-W, FCC ID: BEJTLVUW3IU-W, FCC ID: BEJTL-VUM3IU-E, FCC ID: BEJTLVUW3IU-N, FCC ID: BEJTLVUM3IU-N, FCC ID: NT8-FPK815DTR2, FCC ID: NBGFS19015, FCC ID: NBGFS195, FCC ID: BEJ-ICAS3GP, FCC ID: NBGFS1915, FCC ID: BEJTLVLM3IU-N, FCC ID: BEJTLVUW3IU-W, FCC ID: BEJTLVUW3IU-N, FCC ID: BEJTL-VUM3IU-W, FCC ID: BEJTLVUM3IU-N, FCC ID: BEJTLVUM3IU-E, FCC ID: BEJTLVUE4IU-E, FCC ID: BEJTLVUE4IU-N, FCC ID: BEJTL-VUE4IU-W, FCC ID: QZ9-DCB, FCC ID: 2BAHD-EC30693, FCC ID: YGONFCTGSAU336, FCC ID: KR5I22U, FCC ID: BEJ-MIB30IVR-E01, FCC ID: BEJ-MIB301, FCC ID: BEJ-MIB3GP, FCC ID: YGONFCTG-SAU336, FCC ID: YGOBUEGELNFC, FCC ID: YGOFULSHNFC, FCC ID: 2A6TC-HFA30, FCC ID: T8GCONMODMQB, FCC ID: KR5I2B, FCC ID: KR5I25U, FCC ID: 2A6WXXWCKSD11A, FCC ID: T8GCONMODMEB, FCC ID: OYGTSSSH4, FCC ID: 2A6TC-NFCGATEWAY .

Interference Statement

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

CAUTION TO USERS: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

FCC RF Exposure Statement

FCC ID: RK7MBC-NAR

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. End users must follow the specific operating instruction for satisfying RF exposure compliance. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

This is a CONSUMER device.

BEFORE USE, you MUST REGISTER THIS DEVICE with your wireless provider and have provider's consent. Most wireless providers consent to the use of signal boosters. Some providers may not consent to the use of this device on their network. If you are unsure, contact your provider.

You MUST operate this device with approved antennas and cables as specified by the manufacturer. Antennas MUST be installed at least 20 cm (8 inches) from any person.

You MUST cease operating this device immediately if requested by FCC or a licensed wireless service provider.

WARNING: E911 location information may not be provided or may be inaccurate for calls served by using this device.

- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

- Consult the dealer or an experienced radio/TV technician for help.



Wireless Notice

This device complies with FCC radiation exposure limits set forth for an uncontrolled environment and meets the FCC radio frequency (RF) Exposure Guidelines. This transmitter must not be colocated or operating in conjunction with any other antenna or transmitter.

FCC Class A digital device notice

NOTE: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

FCC Class B digital device notice

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.

Canada

Certificates / Certificats

More entries at / Plus d'entrées sur :
www.volkswagen.com/generalinfo

IC ID / type designator:

IC: 11505A-A
IC: 11505A-MEDIUM5C
IC: 11505A-MEDIUM5C21
IC: 11505A-COULOUR5C
IC: 1788F-UGZZF2
IC: 23650-17101001
IC: 23650-17101002
IC: 23650-17101010
IC: 23650-17101031
IC: 23650-17101033
IC: 23650-17101034
IC: 23650-17101041
IC: 23650-17101042
IC: 23650-17101043
IC: 23650-17101051
IC: 23650-17101052
IC: 23650-17101053
IC: 23650-17101054
IC: 23650-171010101
IC: 23650-18020531
IC: 23650-18020532
IC: 23650-18020533
IC: 23650-18020534
IC: 23650-18100931
IC: 24305-BR20
IC: 24305-BR21
IC: 24305-BR22
IC: 26574-WPC00301
IC: 2694A-009066T
IC: 2694A-013854
IC: 2694A-10176
IC: 2694A-9068
IC: 2694A-92596263
IC: 2694A-BCMEVO
IC: 2694A-BCMEVOS
IC: 2694A-BCM2R
IC: 2694A-BSD30
IC: 2694A-FS09P03
IC: 2694A-FS12A01
IC: 2694A-FS12P01
IC: 2694A-FS12P01M
IC: 2694A-FS125C1
IC: 2694A-FS125C5
IC: 2694A-FS1271M
IC: 2694A-FS173NF

IC ID / type designator:

IC: 2694A-FS173NP
IC: 2694A-FS173NPM
IC: 2694A-FS173NR
IC: 2694A-FS19
IC: 2694A-FS191
IC: 2694A-FS93N
IC: 2694A-LCA20A
IC: 2694A-MQBA
IC: 2694A-MQBBS
IC: 2694A-MQBBSH
IC: 2694A-PQ12P01
IC: 2694A-RS4
IC: 2694A-RSB19
IC: 2703H-LGBTM
IC: 2703H-MEBICAS3
IC: 2703H-MIB2
IC: 2703H-MIB2PQ
IC: 2703H-MIBICAS301
IC: 2703H-TLAHW3IUN
IC: 2703H-TLVHE4IUN
IC: 2703H-TLVHM3IUN
IC: 2703H-TLVLM3IUN
IC: 2703K-TUVM01IU
IC: 3043A-VWMIBREGIO
IC: 3659A-R3TR
IC: 3702A-TSSRE4UD
IC: 3702A-TSSRE4UF
IC: 3702A-TSSSG4G5
IC: 3887A-FRS5CPEC
IC: 3887A-LRR35CU
IC: 3887A-LRR4
IC: 3887A-LRR4R
IC: 3887A-MRRE14FCR
IC: 3887A-MRREVO14F
IC: 3887A-MRR1PLUS
IC: 3887A-MRR1REAR
IC: 4112A-ADHLS5
IC: 4112A-JCIBUSHL4
IC: 4135A-ARS4B
IC: 4135A-ARS5B
IC: 4774A-18500
IC: 4774A-18600
IC: 4774A-MBCNAR
IC: 4774A-NARMMC
IC: 4983A-BNFHL
IC: 4983A-BNFLL
IC: 6369A-ME919BS567B
IC: 6369A-ME919BS567BB
IC: 6434A-A270
IC: 6434A-P114
IC: 772C-LB1FD
IC: 772C-LB1KD
IC: 7812D-BCMEVOC
IC: 7812D-FS14T
IC: 7812D-RX1434
IC: 7812D-SNA920791A

IC ID / type designator:

IC: 7812D-BCM37WBL
IC: 7830A-ALAS6AUS
IC: 7847A-HT5
CAN ICES-3 (B)/NMB-3(B)
IC: 3887A-F5CP42
IC: 2694A-R553
IC: 3887A-FR5CUEC
IC: 2694A-R555
IC: 2694A-LCA20A
IC: 2694A-BSD30
IC: 2694A-R54
IC: 216R-MIB3HBT
IC: 2703H-TLVHM3IUN
IC: 4774A-MBCNAR2
IC: 26574-WPC00305
IC: 26574-WPC00301
IC: 11980A-DDAECE02
IC: 24305-BR22
IC: 3043A-FPK815DTR2
IC: 2694A-FS191S
IC: 2694A-FS1901S
IC: 2694A-FS19S
IC: 2023AJ3293-ICAS3CHNGP
IC: 2703H-ICAS3GP
IC: 2703H-TLVUM3IUN
IC: 2703H-TLVUW3IUN
IC: 4112A-ADHLS
IC: 4008C-NFTGSAU336
IC: 7812C-UWBTRX22
IC: 2703H-MIB3OI
IC: 2703H-MIB3OIVRE01
IC: 2703H-MIB3GP
IC: 28616-HFA30
IC: 4774A-WCH304
IC: 5927A-SCB
IC: 4008C-FLUSHNFC
IC: 4008C-BUEGELNFC
IC: 7812D-5235RXI
IC: 7812D-I25B
IC: 7812D-I25U
IC: 6434A-CONMODMQB
IC: 28616-NFCGATEWAY

IC ID / type designator:

IC: 4774A-18500
IC: 5927A-KA3
IC: 5927A-DCB

IC ID / type designator:

IC: 2703H-LCW05VWE5
IC: 2703H-TLVHE4IUN
IC: 3043A-FPK81MMO5D
IC: 3702A-TSSRE4UF
IC: 3887A-MRRE14FCR
IC: 3887A-MRREVO14F

IC ID / type designator:

IC: 3887A-LRR3CU
IC: 3887A-LRR4R
IC: 3887A-MRR1PLUS
IC: 3887A-MRR1REAR
IC: 4135A-ARS4B

IC ID / type designator:

IC: 4774A-MBCNAR
IC: 4774A-MBCNAR2



Japan / 日本

証明書

その他のエントリ:

www.volkswagen.com/generalinfo

本製品は、電波法に基づく特定無線設備の技術基準適合証明などを受けております。認証番号: XXX-ABCDEF.

本製品の改造は禁止されています。(適合証明番号などが無効となります。)

認証番号:

001-P01084

003-170137

018-190078

018-190080

020-180065

020-180126

020-190017

020-190190

022-190152

201-135167

201-140244

201-140245

201-150312

201-152950

201-160236

201-160528 /00

201-160529 /00

201-170699

201-180834

201-190131 /04

201-190131 /06

認証番号:

202-LSA050

202-LSB041

202-LSC006

202-LSC039

202-LSC054

202-LSE009

202-LSE012

202-LSF030

202-LSG051

202-LSG060

202-LSG061

202-LSJ004

202-5MH049

203-JN0638

203-JN0825

204-250008

204-250009

204-450001

204-550004

204-750001

208-160018

219-210013

219-210016

219-210014

201-190131/06

219-210022

201-190131/07

201-190131

202-LSC054

202-LSE012

認証番号:

㊦ 202-LSA050

㊦ 202-LSC006

㊦ 202-LSF030

㊦ 202-LSC039

㊦ 202-JKM012

㊦ 202-JKM013

㊦ 210-202067

㊦ 220-JPS871

㊦ R210-205889

㊦ R210-205889

㊦ 005-102365

㊦ 022-220038

㊦ 202-SMK077

㊦ 201-240404/00

㊦ 003-240315

㊦ P250011003

㊦ 209-J00509

㊦ 219-250016

㊦ 003-250331

認証番号:

㊦ MDE_VIS_1710

㊦ JN0638 i01

㊦ 202YK08560751

㊦ 204Y50900500

㊦ 204Y50900600

㊦ 204Y51100600

㊦ BL-EC2090896-401

㊦ 2170685R-RF-JP-P01v03

認証番号:

㊦ D14 0046 201

㊦ D18 0207 201

㊦ ADF22-0042018

総務省指定, 第 xx-123456 号

EC-19013

EC-20012

AC-24055

AC-24056

AC-24057

CC-23001

Taiwan (Republic of China) / 臺灣

證書

更多條目位於：

www.volkswagen.com/generalinfo

認可編號

CCAB09LP1540T2

CCAB09LP303BT3

CCAB10LP3800T1

CCAB10LP418AT1

CCAB10LP418FT1

CCAB10LP418GT0

CCAB10LP418HT2

CCAB10LP418IT4

CCAB10LP418JT6

CCAB10LP418KT8

CCAB11LP0160T7

CCAB12LP1890T5

CCAB12LP472AT0

CCAB12LP4720T8

CCAB12LP473AT0

CCAB12LP4730T1

CCAB13LP0350T2

CCAB13LP2210T9

CCAB14LP1210T2

CCAB14LP5770T5

CCAB15LP4630T5

CCAB16LP1220T5

CCAB16LP1830T6

認可編號

CCAB16LP3140T4

CCAB17LP0470T5

CCAB184G0020T2

CCAB194G0060T9

CCAB19LP107A

CCAB19LP107BT1

CCAB19LP1070T0

CCAB19LP1070TOT2

CCAB204G0050T8

CCAE15LP0170T7

CCAF133G0880T6

CCAE15LP0170T7

CCAE15LP0180T0

CCAE15LP0190T0

CCAE15LP1050T2

CCAE15LP1290T9

CCAE16LP0320T8

CCAE17LP0940T7

CCAF11LP1000T4

CCAF133G0880T6

CCAF16LP2450T2

CCAH14LP0500T1

CCAH14LP0510T1

CCAH15LP0300T1

CCAH15LP0310T1

CCAH15LP2290T5

CCAH16LP1820T1

CCAH16LP2450T9

CCAH17LP3640T1

CCAH18LP1680T1

認可編號

CCAH18LP2200T2

CCAH18LP3860T0

CCAH19LP5860T2

CCAH19LP7110T8

CCAH20LP0380T4

CCAH20LP9630T7

CCAI14LP1910T6

CCAI15LP0220T0

CCAI15LP1570T3

CCAI15LP1580T6

CCAI19LP0370T9

CCAI19LP1390T7

CCAJ13LP0670T9

CCAJ13LP0690T2

CCAJ19LP2080T7

CCAJ19LP2081T9

CCAJ20LP0370T8

CCAJ20LP0380T1

CCAK15LP0801T1

CCAK16LP1510T0

CCAK19LP0370T3

CCAK21LP0700T8

CCAL18LP0610T2

CCAL18LP0850T6

CCAL18LP1020T9

CCAL18LP1030T2

CCAL18LP1190T8

CCAL18LP1200T1

CCAL18LP1210T1

CCAL18LP1240T0

認可編號

CCAL18LP1410T9

CCAL18LP1430T2

CCAL18LP1440T5

CCAL18LP1460T1

CCAL18LP1480T4

CCAL18LP1560T2

CCAL18LP1570T5

CCAL18LP1580T8

CCAL18LP1590T1

CCAL18LP1600T1

CCAL18LP1610T4

CCAL18LP1620T7

CCAL18LP1730T1

CCAL18LP1740T4

CCAL18LP1750T7

CCAL18LP1820T2

CCAL18LP240T0

CCAL19LP0560T5

CCAL19LP0580T1

CCAL19LP2450T8

CCAL19LP2460T1

CCAL20LP036T2

CCAM18LP1840T5

CCAM20LP0390T

CCAM20LP0390T5




































CCAN15LP0030T3

CCAN15LP0260T7

CCAN15LP0270T0

CCAN16LP0330T0

CCAN17LP0530T0

認可編號 CCAN17LP0540T3 CCAN17LP0550T6 CCAN18LP0960T7 CCAN184G0010T2 CCAN19LP0750T7 CCAN19LP0760T7 CCAN20LP0620T6 CCAO17LP040BT1 CCAO17LP040CT3 CCAO17LP0740T8 CCAO17LP0750T1 CCAO17LP0770T4 CCAO17LP0790T9 CCAO194G008AT4 CCAO194G008OT2 CCAO20LP054AT7 CCAO20LP054OT5 CCAO20LP187OT5 CCAO21LP0690T6 CCAQ21LP0040T0 CTL093LPD0207 CTL093LPD0208 CTL093LPD0209 CTL093LPD0210 CTL093LPD0211 CCAK21LP0700T8 CI360062160903 CI1361062161041 CCAO20LP187OT5 CCAH22LP3160T8**認可編號** CCAN184G0010T2 CCAK21LP0700T8 CCAF22LP0920T6 CCAF22LP1030T4 CCAJ19LP2081T9 CCAJ22LP3CD0T4 CCAJ22LP3CE0T7 CCAB13LP2210T9 CCAF22LP1860T6 CCAF22LP1850T3 CCAF22LP1840T0 CCAF22LP1960T0 CCAF22LP1950T7 CCAI1922LP0370T9 CCAL22LP1200T1 CCAO22LP0190T2 CCAK21LP0700T8 CCAH22LP1570T4 CI33006724A685 CI33106724B888 CCAO23LP0090T1 CCAH23LP2450T7 CCAH23LP4560T1 CI369062160804 CI369062160826 CI362072160800 CCAH22LPA120T2 CCAH22LPA130T2 CCAO23LP0790T0 CCAO23LP0780T0

認可編號

CCAB16LP3140T4

CCAL234G0060T5

CCAL234G0050T2

CCAH235G0090T7

CI362062161150

CCAL23LP0230T0

CCAL23LP0230T0

CCAH22LPB090T8

CCAL24LP0300T0

CCAF24LP0920T6

CI430066810546

CCAL24LP0300T0

CCAL24LP0300T0

CCAL24LP0340T2

CCAB24LP0620T9

CCAL24LP0540T7

CCAB24LP1050T2

CI363062161342

CI364062161451

CCAH255G0140T2

CCAI25LP0440T7

CI33106724B888

CCAF25LP0690T0

CCAF25LP0680T0

CI364062161470

CCAB25LP1020T1

CCAL25LP1060T6

20251028000013

CCAH25LPC130T0

CI362062161150

取得審驗證明之低功率射頻器材，非經核准，公司、商號或使用者均不得擅自變更頻率、加大功率或變更原設計之特性及功能。低功率射頻器材之使用不得影響飛航安全及干擾合法通信；經發現有干擾現象時，應立即停用，並改善至無干擾時方得繼續使用。前述合法通信，指依電信管理法規定作業之無線電通信。低功率射頻器材須忍受合法通信或工業、科學及醫療用電波輻射性電機設備之干擾。 ◀












Republic of Korea / 대한민국

인증서

더 많은 항목:









www.volkswagen.com/generalinfo

승인번호, 주파수 대역, 최대 송신 출력









	HLA-010180-61, 315 MHz, 54 dB μ V/m @ 3m (peak)
	HLA-010206-60, 433,92 MHz, 0,4 mW (EIRP)
	MSIP-CRM-HLA-FS1743, 433,92 MHz, 0,36 mW (EIRP)
	MSIP-CRM-HLA-FS94K, 433,92 MHz, 0,36 mW (EIRP)
	MSIP-RRM-HLA-FS93K, 315 MHz, 54 dB μ V/m @ 3m (peak)
	R-C-HLA-FS125C3, 433,92 MHz, 0,36 mW (EIRP)
	R-C-TAL-FS14T, 433,92 MHz, 30 μ W
	R-C-TAL-FS14TK, 433,92 MHz, 30 μ W
	R-CRM-HLA-FS12P03M, 433,92 MHz, 0,36 mW (EIRP)
	R-CRM-HLA-FS1743M, 433,92 MHz, 0,36 mW (EIRP)
	R-CRM-MQU-VK2, 433,05 MHz - 434,79 MHz, 1 mW (EIRP)

이 기기는 가정용(B급) 전자파적합기기로서 주로 가정에서 사용하는 것을 목적으로 하며, 모든 지역에서 사용할 수 있습니다.

승인번호



















	KCC-CRM-HLA-FS12P03
	KCC-CRM-HLA-FS12A04
	R-C-HLA-FS1903
	R-C-HLA-RSB19
	R-CRM-MQU-VK2
	R-R-HLA-013854
	R-C-HLA-FS1903S
	R-C-HLA-FS1913S

승인번호

	R-R-HLA-013854
	R-R-JnX-MIB30InF
	R-R-B2U-SCB
	R-C-T8G-TKCMOD12E00W
	R-R-vT2-HFA31
	R-C-TeH-I25U
	R-R-vT2-NFCGATEWAY
	R-C-T8G-TKCMOD12E00W

이 기기는 가정용(B급) 전자파적합기기로서 주로 가정에서 사용하는 것을 목적으로 하며, 모든 지역에서 사용할 수 있습니다.

승인번호

	B02-LRR3
	MISP-CMM-B02-LRR4
	MSIP-CRI-BCS-MRR1Plus
	MSIP-CMM-B02-MRR1Rear
	MSIP-CMM-HLA-BSD3.0M
	MSIP-CMM-HLA-BSD3.0S
	MISP-RMM-N7V-WCH-186
	R-C-T8G-CONBOX-HIGH
	R-CMM-B02-MRRRevo14F
	R-CMM-HLA-RS4
	R-C-BAC-ARS5-B
	R-C-B02-F5CP42
	R--CMM-B02-MRRRevo14F
	R-R-HEB-TMSE6A4
	R-C-B02-FR5CUEC
	R-C-HLA-RS5_3
	R-C-HLA-RS5_5
	R-R-HLA-013854

승인번호

R-R-VCI-FPK8IMM05D

R-C-HLA-R5B19

R-R-BCS-WPC003-1

R-R-BCS-WPC003-5

R-R-B2U-SCB

R-R-HHF-BUEGELNFC

이 기기는 업무용(A급) 전자파적합기기로서 판매자 또는 사용자는 이 점을 주의하시기 바라며, 가정외의 지역에서 사용하는 것을 목적으로 합니다.

승인번호

HLA-10176

KCC-CRM-B02-LRR3

KCC-RRM-HLA-MQBASG

MSIP-CMM-B02-LRR4

MSIP-CMM-DDG-MIB2STD

MSIP-CMM-HLA-BCM2R

MSIP-CMM-HLA-LCA2

MSIP-CMM-HLA-LCA2.0ASWASG2

MSIP-CMM-N25-MMXF-online

MSIP-CMM-N7V-HT-6d

MSIP-CMM-N7V-LTE-MBC-CN

MSIP-CMM-TD4-MIBSTD2PQ

MSIP-CMM-TD4-MIBSTD2ZRNAV

MSIP-CRI-BCS-MRRevo14F

MSIP-CRM-DDG-R3TR

MCIP-CRM-DDG-R3TR

MSIP-CRM-HEB-TSSRE4DG

MSIP-CRM-N7V-HT-5

MSIP-CRM-8AC-ARS4B

MSIP-CRM-8DC-ARS4B

승인번호

MSIP-REM-B02-BR11

MSIP-REM-HEB-TSSSG4G5

MSIP-RMM-HLA-BCMevo

MSIP-RMM-N7V-WCH-185

MSIP-RRM-HLA-MQB-BB

MSIP-RRM-HLA-MQB-BH

R-C-B02-BR21

R-C-B02-FR5CPEC

R-C-DDG-MIB2PLUS

R-C-HEB-TSSRE4Uf

R-C-P2G-MIB3

R-C-8AC-ARS5B

R-CRM-DDG-R3TR

R-C-HUW-ME919Bs821bNb

R-CRM-MOU-VK2

R-CRM-SWK-AR7598

R-CRM-8AC-ARS4B

R-LPD1-04-0246

R-LPD1-04-0247

R-LPD1-04-0248

R-LPD1-05-0050

R-R-bcS-WPC003-1

R-R-HEB-TSSSG4G5b

R-R-HHF-NFCTGS2

R-R-HLA-BCMevo5































R-R-LGE-LCW05-VWE5
















R-R-LGE-TLVHB4IU-W

R-R-LGE-TLVHM3IU-W

R-R-TAL-BCMevoC

R-R-TAL-MQB-A_B

승인번호	
 R-R-TAL-17101051	
 R-R-TAL-17101052	
 R-R-TAL-17101053	
 R-R-TAL-17101054	
 R-R-TAL-18020532	
 R-R-TAL-18020534	
 R-R-TAL-18100931	
 R-R-VCI-FPK8IMMOSD	
 R-R-VCO-COLOUR5C	
 R-R-VCO-MEDIUM5C	
 R-REM-L2G-CONBOX-LOW	
 R-RMM-TAL-17101001	
 R-RMM-TAL-17101002	
 R-RMM-TAL-17101031	
 R-RMM-TAL-17101032	
 R-RMM-TAL-17101033	
 R-RMM-TAL-17101041	
 R-RMM-TAL-17101043	
 R-RMM-TAL-18020531	
 R-RMM-TAL-18020532	
 R-RMM-TAL-18020533	
 R-RMM-VCO-KOMBI	
 RRM-HLA-MQBASG	
 T8G-MMI3G	
 R-C-HLA-FS1903S	
 R-C-HLA-RSB19	
 R-R-HLA-013854	
 R-R-BCS-WPC003-5	
 R-R-LGE-TLVUW3IU-W	
 R-R-LGE-TLVUM3IU-W	

승인번호	
 R-R-LGE-MEB-ICAS3	
 R-R-LGE-MEB-ICAS3GP	
 OT-22D-RET-004	
 R-R-LGE-ICAS3GP	
 OT-231-RWR-004	
 R-R-vT2-DHSEQ5NFC	
 R-C-N7V-5G-NRC-CN	
 KR23-YEK0604	
 KR23-YEK0605	
 KR23-SRK0246	
 R-R-VC1-FPK815DTR2	
 R-R-TeH-SWK50254	
 R-R-HHF-NFCTGSAU336	
 R-R-LGE-MIB3GP	
 R-R-HHF-FLUSHNFC	

해당 무선 설비는 운용 중 전파혼신가능성이 있음.
해당 무선설비는 운용 중 전파혼신 가능성이 있으므로, 인명 안전과 관련된 서비스는 할 수 없습니다.

이 기기는 업무용(A급) 전자파적합기기로서 판매자 또는 사용자는 이점을 주의하시기바라며, 가정외의 지역에서 사용하는 것을 목적으로 합니다.

이 기기는 가정용(B급) 전자파적합기기로서 주로 가정에서 사용하는 것을 목적으로 하며, 모든 지역에서 사용할 수 있습니다. 해당 무선 설비는 운용 중 전파 혼신 가능성이 있음.

기자재의 명칭 : LTE 이동통신용 무선설비의 기기 (육상이동국의 송수신장치)

상호명 : 엘지전자(주) 제조자 / 제조국가 : 엘지전자(주) / 베트남

